

8/07/24 4:33 PM

59379 GPM # 5637
5499 US HWY 20
SOUTH BEND, IN 46628
74-287-0837

PRESSURE LINE LEAK REPORTS
PASSED TESTS HISTORY

1: UNLEAD

2: DIESEL

3: PREMIUM

8/07/24 4:33 PM

59379 GPM # 5637
5499 US HWY 20
SOUTH BEND, IN 46628
74-287-0837

Sensor Status Report -
All Sensors

DATA AVAILABLE

8/07/24 4:33 PM

59379 GPM # 5637
5499 US HWY 20
SOUTH BEND, IN 46628
74-287-0837

PANK LEAK TEST HISTORY -
PASSED TEST RESULTS

1: UNLEAD

REPORT TYPE = LAST GROSS
DATE/TIME = 08/07/24 2:47
METHOD = SLD Gross Test
WG. VOLUME = 8923
VOLUME = 74.2

REPORT TYPE = LAST PERIODIC
DATE/TIME = 08/07/24 3:22
METHOD = CSLD Periodic Test
DURS = 23
WG. VOLUME = 4733
VOLUME = 39.3

REPORT TYPE = FULLEST PERIODIC
DATE/TIME = 08/05/24 3:09
METHOD = CSLD Periodic Test
DURS = 23
WG. VOLUME = 4943
VOLUME = 41.1

REPORT TYPE = FULLEST PERIODIC
DATE/TIME = 07/07/24 5:06
METHOD = CSLD Periodic Test
DURS = 22
WG. VOLUME = 6391
VOLUME = 53.1

REPORT TYPE = FULLEST PERIODIC