

7/05/24 5:01 PM

9379 GPM # 5637
499 US Hwy 20
OUTH BEND, IN 46628
4-287-0837

RESSURE LINE LEAK REPORTS
ASSED TESTS HISTORY

1: UNLEAD

2: DIESEL

3: PREMIUM

7/05/24 5:02 PM

9379 GPM # 5637
499 US Hwy 20
OUTH BEND, IN 46628
4-287-0837

ensor Status Report -
1 Sensors

DATA AVAILABLE

7/05/24 5:02 PM

9379 GPM # 5637
499 US Hwy 20
OUTH BEND, IN 46628
4-287-0837

ANK LEAK TEST HISTORY -
ASSED TEST RESULTS

1: UNLEAD

PORT TYPE = LAST GROSS
TE/TIME = 07/05/24 4:00
THOD = SLD Gross Test
G. VOLUME = 3768
VOLUME = 31.3

PORT TYPE = LAST PERIODIC
TE/TIME = 07/05/24 4:44
THOD = CSLD Periodic Test
URS = 27
G. VOLUME = 5862
VOLUME = 48.7

PORT TYPE = FULLEST PERIODIC
TE/TIME = 07/01/24 2:56
THOD = CSLD Periodic Test
URS = 24
G. VOLUME = 6241
VOLUME = 51.9

PORT TYPE = FULLEST PERIODIC
TE/TIME = 06/01/24 3:40
THOD = CSLD Periodic Test
URS = 23
G. VOLUME = 6743
VOLUME = 56.0

PORT TYPE = FULLEST PERIODIC
TE/TIME = 05/19/24 6:10
THOD = CSLD Periodic Test
URS = 23
G. VOLUME = 7395
VOLUME = 61.5

PORT TYPE = FULLEST PERIODIC
TE/TIME = 04/28/24 7:22
THOD = CSLD Periodic Test