	30 DAYS WALK THROUGH INSPECTION						
Tanks Data							
JST Facility I.D.((FID)# 15670		Contact Number					
Facility Name		Contact email					
Address 7 649905 Hwy 200		Date of Inspection $10-25-7025$					
Operator on Duty Name	4862	Name of the Conducting		Crupree	1		
	Ор	erator Train					
Operator	Training current	Yes	No	OperatorNotified	Yes	ONo.	
	Registrat	tion/Notificat	ion Form		_		
Is Registration current w	ith correct owner, operator etc.	Yes	ONo	OperatorNotified	Yes	Olo	
		lease Detecti	on				
the search of the property of	Detection Method	CATG	C IM	BIR	Oic	Other	
Make	e and Model () - 4	0 VN	1				
Does it have paper?		Yes	ONo	OperatorNotified	Yes	Olo	
Is it in Alarm mode?		Yes	ONO	OperatorNotified	Yes	Olo	
Interstitial Monitoring Sensor Status Normal		Yes	No	OperatorNotified	Yes	ONO	
Necessary Monthly Printout Taken		Yes	ONO	OperatorNotified	Yes	Ovo	
		Spill Buckets					
Are Spill Buckets Clean and free from water, debris, product etc?		Ores	(P)No	OperatorNotified	(A)es	Olo	
Are the Spill Bucket in good condition and free of damage/cracks		Yes	ONO	OperatorNotified	(7)es	No	
		Ful Ports			_	_	
Is Fill pipe cap tight and fi	Il pipe free from any obstruction?	Yes	Ovo	OperatorNotified)es	Olo	
	Pi	ping/STP Sur	nps		_		
Are Sumps Clean and free	from water, debris, product etc?	(W)Yes	Olo	OperatorNotified	O'res	Oio	
	Under Dispe	nser Contain	ments (UD	C)			
Are UDCs clean and free	from water, debris, product etc?	Yes	ONO	OperatorNotified	Ores	Olo	
NOTE: ALL LIQUID/I	DEBRIS OR WASTE MUST BE DISPO FOLLOWING PROPER PRO				AND REQU	JLATIONS	
Operator on Duty Name			Signatur	re C	Date		
317-645-0215	317-645-0215 tanksdata@gmail.com					www.tanksdata.com	
						2022051	