Tanks Data	30	DAYS WA	LK THROUGH	INSPECT	FION
UST Facility I.D.((FID)# 8958	Contact Number				
Facility Name Chyphexthery	Contact email				
Address 914 = Zerator was Cers 23	Date of Inspection 69-77-1005				
Operator on Duty Name	Name of the P Conducting Ir		Surbree	1	
Op	erator Training				_
Operator Training current	Yes	ONo	OperatorNotified	Yes	(No
Registration current with correct owner, operator etc.	ion/Notification  Yes	Form	OperatorNotified	Ores	Oio
$\mathbb{R}^{\epsilon}$	lease Detection				
Release Detection Method	ATG	DIM	SIR	OIC	Other
Make and Model ( )	Yes	(No	OperatorNotified	Yes	Oio
Is it in Alarm mode?	Yes	ONO	OperatorNotified	Yes	(No
Interstitial Monitoring Sensor Status Normal	Yes	No	OperatorNotified	Yes	No
Necessary Monthly Printout Taken	Yes	No	OperatorNotified	Tes	ONO
	Spitt Buckets				
Are Spill Buckets Clean and free from water, debris, product etc?	Yes	No	OperatorNotified	- Oes	Olo
Are the Spill Bucket in good condition and free of damage/cracks	Ores	No	OperatorNotified	(7)es	()io
	Fill Ports				
Is Fill pipe cap tight and fill pipe free from any obstruction?	Yes	( No	OperatorNotified	( )es	( )io
사용하는 사용하는 사용하는 사용하는 사용하는 사용하는 사용하는 사용하는	ping/STP Sum	ps			
Are Sumps Clean and free from water, debris, product etc?	Wes	( )Vo	OperatorNotified	Yes	( )Vo
하는 사람들이 되었다. 그는 사람들이 되었다면 그는 사람들이 되었다. 그는 사람들이 되었다면 그는 사람들이 그는 사람들이 되었다면 그는 사람들이 그	enser Containm	ients (UDC)			
Are UDCs clean and free from water, debris, product etc?	Yes	( No	OperatorNotified		( )Yo
NOTE: ALL LIQUID/DEBRIS OR WASTE MUST BE DISP FOLLOWING PROPER PRO	OSSED OFF A	CCORDING :	TO EXISTING RULE.	S AND REQU	JLATIONS
perator on Duty Name		Signature		Date	
317-645-0215 tanks	data@gmail.co	m _		www.tanks	edata com
DOI/IND	anna Carpentalia.	• • • • • • • • • • • • • • • • • • • •		AA AA AA' CCITIIN'	Sagra, VVIII