

001
Tanks Data

30 DAYS WALK THROUGH INSPECTION

UST Facility I.D. (RID) # 18662

Contact Number

Facility Name MARRAMON

Contact email

Address 3901 S Minst, Street, IN

Date of Inspection 08/15/24

Operator on Duty Name

Name of the Person Conducting Inspection

46516

AKSHIT

Operator Training current

Operator Training
☐ Yes ☐ No

Operator Notified

☐ Yes

☐ No

Is Registration current with correct owner, operator etc.

Registration/Notification Form
☐ Yes ☐ No

Operator Notified

☐ Yes

☐ No

Release Detection Method

Release Detection
☒ ATG ☐ DIM

☐ SIR

☐ JC

☐ Other

Make and Model

FFS TS1001

Does it have paper?

☒ Yes

☐ No

Operator Notified

☒ Yes

☐ No

Is it in Alarm mode?

☒ Yes

☐ No

Operator Notified

☒ Yes

☐ No

Interstitial Monitoring Sensor Status Normal

Necessary Monthly Printout Taken

☐ Yes

☐ No

Operator Notified

☒ Yes

☐ No

Spill Buckets

☐ Yes

☒ No

Operator Notified

☒ Yes

☐ No

Are Spill Buckets Clean and free from water, debris, product etc?

☒ Yes

☐ No

Operator Notified

☒ Yes

☐ No

Are the Spill Bucket in good condition and free of damage/cracks

☒ Yes

☐ No

Operator Notified

☒ Yes

☐ No

Is Fill pipe cap tight and fill pipe free from any obstruction?

☒ Yes

☐ No

Operator Notified

☐ Yes

☐ No

Pipeline/STP Sumps

☐ Yes

☒ No

Operator Notified

☒ Yes

☐ No

Are Sumps Clean and free from water, debris, product etc?

☐ Yes

☒ No

Operator Notified

☒ Yes

☐ No

Are UDCs clean and free from water, debris, product etc?

☐ Yes

☒ No

Operator Notified

☒ Yes

☐ No

NOTE: ALL LIQUID/DEBRIS OR WASTE MUST BE DISPOSED OFF ACCORDING TO EXISTING RULES AND REGULATIONS FOLLOWING PROPER PROCEDURE BY A CERTIFIED CONTRACTOR.

Operator on Duty Name

Signature

Date

317-645-0215

tanksdata@gmail.com

www.tanksdata.com

20220516