onl	30 DAYS WALK THROUGH INSPECTION						
Tanks Data							
UST Facility I.D.((FID)# 18662		Contact Number					
Facility Name Manale		Contact email					
Address 3 901 S Main St 4/512		Date of Inspection 09-29-2075					
Operator on Duty Name		Name of the Person Conducting Inspection  Guyloreet					
	Op	erator Train	ning				
Operator	Training current	Yes	ONo	OperatorNotified	Yes	ONo	
Registration/Notification Form							
Is Registration current w	rith correct owner, operator etc.	Yes	(No	OperatorNotified	Ves	Olo	
Palanca D	etection Method	lease Detect		OTIP	Orc	Owhere	
	The state of the s	ATG	EIM,	BIR	Oic	Other	
Make and Model 7 - / 60 / 4.  Does it have paper?		O Ves	Schon	OperatorNotified	Yes	No	
Is it in Alarm mode?		Yes	No	OperatorNotified	Yes	No	
Interstitial Monitoring Sensor Status Normal		Yes	No	OperatorNotified	Yes	No	
Necessary Monthly Printout Taken		Yes	No	OperatorNotified	Tes	No	
		Spill Bucket	is				
Are Spill Buckets Clean and free from water, debris, product etc?		Ores	ONO	OperatorNotified	(Ses	Olo	
Are the Spill Bucket in good condition and free of damage/cracks		Q Yes	ONO	OperatorNotified	es	Olo	
		Fill Ports				~	
Is Fill pipe cap tight and fill	l pipe free from any obstruction?	Yes	ONO	OperatorNotified	Oes	Oio	
	ket (1995년 1996년 - 1995년 1996년 1996년 1996년 1996년 1996년 1997년 1996년 1996년 1997년 1997년 1997년 1997년 1997년 1997년 1	ing/STP Su	mps				
Are Sumps Clean and free	from water, debris, product etc?	Yes	O/lo	OperatorNotified	Ves	Olo	
			nments (UDC	1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1			
Are UDCs clean and free f	from water, debris, product etc?	Yes	No	OperatorNotified	O és	Olo	
NOTE: ALL LIQUID/D	EBRIS OR WASTE MUST BE DISPO FOLLOWING PROPER PRO				AND REQU	JLATIONS	
Operator on Duty Name			Signature	:	Date		
317-645-0215	tanksd	tanksdata@gmail.com wv				sdata.com	
				3			20220516