00[] *					
Tanks Data	30	DAYS W	ALK THROUG	H INSPE	CTIO
UST Facility I.D.((FID) # 1633 Facility Name Common	Contact Nu				0110
Address 12/15 O	Contact email				
Address 1245 S Main St ElKhart 46516 Operator on Duty Name	Date of Insp		3/31/22		
The state of the s	Name of the	Person			
	Conducting	Inspection	_Josh Ri	der	
Operator Training current	perator Traini	0			
	Yes ation/Notificati	ŬN ₀	OperatorNotified	Ores	(
Is Registration current with correct owner, operator etc.	Yes Yes	No	Onemate Note:	0	
	elease Detection	n Olo	OperatorNotified	Ves	(
Release Detection Method	✓ ATG	CIM	SIR	OIC	
Make and Model	Franklin	FS TS	- 1001	Oc	(
Does it have paper?	Yes	ONo	OperatorNotified	Yes	(
Is it in Alarm mode?	Yes	No	OperatorNotified	Yes	>
Interstitial Monitoring Sensor Status Normal	(V) res	No	OperatorNotified	Yes	>
Necessary Monthly Printout Taken	Yes	O _{No}	OperatorNotified) res	~
Are Spill Buckets Clean and free from water, debris, product etc?	Spill Buckets	~			
Are the Spill Bucket in good condition and free of damage/cracks	Ves	Ø/o	OperatorNotified	Oes	
and the opin backet in good condition and free of damage/cracks	Yes Fill Ports	O_{N^0}	OperatorNotified	Oes .	
Is Fill pipe cap tight and fill pipe free from any obstruction?	Yes	No	OperatorNotified	0	
	ping/STP Sum	0.0	Operator (totalled	Jes	
Are Sumps Clean and free from water, debris, product etc?	O/es	No	OperatorNotified	()res	(
Under Disp	enser Containm	ients (UDC)	_	0	
Are UDCs clean and free from water, debris, product etc?	OYes .	No	OperatorNotified	O'es	(
NOTE: ALL LIQUID/DEBRIS OR WASTE MUST BE DISF FOLLOWING PROPER PRO	OSSED OFF A	CCORDING T	TO EXISTING RULES	AND REQUI	LATIO
Operator on Duty Name	-DODDIA (Signature	OMMON TOR.	Date	
317-645-0215 tanks	data@gmail.com	n		www.tanksd	ata.com

DIESEL 10153.0 GAL DIESEL

SLOPE 0.028 GAL/HR TEST RESULT PASSED SLOPE EQUALS CALCULATED LEAK RATE

PREMIUM 12033.0 GAL PREMIUM

LEAK TEST 0.200 GPH LEAK THRESHOLD 0.100 GPH INTERVAL 18.0