

872051 SAMPLE ST
4023 W SAMPLE
SOUTH BEND, IN 46619

DEC 22, 2024 6:41 PM

CSLD TEST RESULTS

DEC 22, 2024 6:41 PM

T 1:UNL

PROBE SERIAL NUM 363159

0.2 GAL/HR TEST

PER: DEC 22, 2024 PASS

T 2:PLUS

PROBE SERIAL NUM 363200

0.2 GAL/HR TEST

PER: DEC 22, 2024 PASS

T 3:PREMIUM

PROBE SERIAL NUM 366409

0.2 GAL/HR TEST

PER: DEC 22, 2024 PASS

T 4:KEROSENE

PROBE SERIAL NUM 364080

0.2 GAL/HR TEST

PER: DEC 22, 2024 PASS

* * * * * END * * * * *

872051 SAMPLE ST
4023 W SAMPLE
SOUTH BEND, IN 46619

DEC 22, 2024 6:41 PM

LEAK TEST REPORT

T 1:UNL

PROBE SERIAL NUM 363159

NO TEST DATA AVAILABLE

* * * * * END * * * * *

872051 SAMPLE ST
4023 W SAMPLE
SOUTH BEND, IN 46619

DEC 22, 2024 6:41 PM

LEAK TEST REPORT

T 2:PLUS
PROBE SERIAL NUM 363200

NO TEST DATA AVAILABLE

* * * * * END * * * * *

872051 SAMPLE ST
4023 W SAMPLE
SOUTH BEND, IN 46619

DEC 22, 2024 6:41 PM

LEAK TEST REPORT

T 3:PREMIUM
PROBE SERIAL NUM 366409

NO TEST DATA AVAILABLE

* * * * * END * * * * *

872051 SAMPLE ST
4023 W SAMPLE
SOUTH BEND, IN 46619

DEC 22, 2024 6:41 PM

LEAK TEST REPORT

T 4:KEROSENE
PROBE SERIAL NUM 364080

NO TEST DATA AVAILABLE

* * * * * END * * * * *