Tanks Data	30 DAYS WALK THROUGH INSPECTION					
UST Facility I.D.((FID) # 7 × 07	Contact Number					
Facility Name	Contact email					
Address 4023 W Camboo 5+ 46619	Date of Inspection $0/-12-2025$					
Operator on Duty Name	Name of the Person Conducting Inspection Greekaat					
	Operator Trai					
Operator Training current	Yes	ONo	OperatorNotified	Yes	ONo	
YOU NOTE HEAD NOT HEAD NOTE HEAD NO	ation/Notifica	ation Form				
Is Registration current with correct owner, operator etc.	Yes	ÛN ₀	OperatorNotified	Ves	ONO	
I	Release Detect		On 17	0.0		
Release Detection Method	⊘ ATG	CIM	OBIR	Oic	Other	
Make and Model VRTLS -3 50		_		0	0	
Does it have paper?	Yes	ON ₀	OperatorNotified	Yres	240	
Is it in Alarm mode?	Yes	ONo	OperatorNotified	Yes	Q\v0	
Interstitial Monitoring Sensor Status Normal	Yes	ONO	OperatorNotified	Yes	Ονο	
Necessary Monthly Printout Taken	Yes	ONo	OperatorNotified	Ores	O _{No}	
경우 마음을 하는 것을 받는 것이 되었다. 그는 것으로 보는 이 이 기를 보고 있는 것으로 보고 있는 것이 되었다. 그는 것은 사람들은 것으로 하는 것으로 함께 되었다. 경우는 사람들은 것이 되었다. 그는 것은 것은 것은 전략을 하는 것이 되었다. 그런 것은 것은 것은 것은 것은 것은 것은 것은 것이 되었다. 그런 것은 것은 것은 것은 것을 했다. 것은 것을 했다.	Spill Buckets	s				
re Spill Buckets Clean and free from water, debris, product etc?	Ves	(%)	OperatorNotified	Ges	Olo	
re the Spill Bucket in good condition and free of damage/cracks	Yes	No	OperatorNotified	es	Olo	
Te the Spin Ducket in good condition and 1100 or among or	Fill Ports				~	
Is Fill pipe cap tight and fill pipe free from any obstruction?	Yes	No	OperatorNotified	Oes	Olo	
Pi _l	oing/STP Sun	nps		~		
Are Sumps Clean and free from water, debris, product etc?	Yes	PNo	OperatorNotified	Ves	Olo	
Under Disper	nser Contain	ments (UDC)		Ø		
Are UDCs clean and free from water, debris, product etc?	Yes	(DNo	OperatorNotified	Pres	Olo	
NOTE: ALL LIQUID/DEBRIS OR WASTE MUST BE DISPO FOLLOWING PROPER PROC	OSSED OFF A	CERTIFIED (TO EXISTING RULES . CONTRACTOR.			
ator on Duty Name		Signature		Date O	(-12-20	
	ata@gmail.co	a@gmail.com			www.tanksdata.com	