

30 DAYS WALK THROUGH INSPECTION

000

TANKS DATA

UST Facility I.D. (FID) # 18719

Contact Number

Facility Name BP

Contact email

Address 8095 W State Road 120, Ash Grove, WI

Date of Inspection 09/16/27

Operator on Duty Name

Name of the Person Conducting Inspection

46565

AKSMT

Operator Training current

Operator Training
☐ Yes ☐ No

Operator Notified

☐ Yes

☐ No

Is Registration current with correct owner, operator etc.

Registration/Notification Form
☐ Yes ☐ No

Operator Notified

☐ Yes

☐ No

Release Detection Method

Release Detection
☒ ATG ☐ CIM

☐ BIR

☐ IC

☐ Other

Make and Model

Does it have paper?

Is it in Alarm mode?

Interstitial Monitoring Sensor Status Normal

Necessary Monthly Printout Taken

Spill Buckets

☐ Yes ☒ No

Operator Notified

☐ Yes

☐ No

Are Spill Buckets Clean and free from water, debris, product etc?

☐ Yes ☒ No

Operator Notified

☐ Yes

☐ No

Are the Spill Bucket in good condition and free of damage/cracks

☐ Yes ☒ No

Operator Notified

☐ Yes

☐ No

Is Fill pipe cap tight and fill pipe free from any obstruction?

Fill Ports
☐ Yes ☒ No

Operator Notified

☐ Yes

☐ No

Are Sumps Clean and free from water, debris, product etc?

Piping/STP Sumps
☐ Yes ☒ No

Operator Notified

☐ Yes

☐ No

Are UDCs clean and free from water, debris, product etc?

Under Dispenser Containment (UDC)
☐ Yes ☒ No

Operator Notified

☐ Yes

☐ No

Operator on Duty Name

Signature

Date

317-645-0215

tanksdata@gmail.com

www.tanksdata.com

20220516

NOTE: ALL LIQUID/DEBRIS OR WASTE MUST BE DISPOSED OFF ACCORDING TO EXISTING RULES AND REGULATIONS FOLLOWING PROPER PROCEDURE BY A CERTIFIED CONTRACTOR.