Tanks Data		3	30 DAYS V	VALK THROUGH	INSPEC	CTION	
UST Facility I.D.( (FID) #	8219 Contact Number						
Facility Name ( )		Contact en	Contact email				
Address 8 095 111 StR 20 46565		Date of Ins	Date of Inspection $64-19-1065$				
Operator on Duty Name			Name of the Person Conducting Inspection  Cualzet				
Operato	r Training current	Operator Train  Yes	No	OperatorNotified	Ores	ONo	
Is Registration current with correct owner, operator etc.		tration/Notifica	tion Form No	OperatorNotified	Ores	Oio	
Release Detection Method		Release Detect	OCIM	OSIR	Oic	Other	
Make and Model VRTLS - 33  Does it have paper?		Yes	ONo	OperatorNotified	QYes	040	
Is it in Alarm mode?  Interstitial Monitoring Sensor Status Normal		Yes	No	OperatorNotified OperatorNotified	Yes	8,0	
Necessary Monthly Printout Taken		Yes See III Bushes	QNo	OperatorNotified	Ores	Ovo	
Are Spill Buckets Clean and free from water, debris, product etc.  Are the Spill Bucket in good condition and free of damage/crack		c? Spill Bucket	No	OperatorNotified OperatorNotified	Ses es	810	
		Fill Ports	ON <sub>0</sub>	OperatorNotified	Ores	ONO	
Is Fill pipe cap tight and	fill pipe free from any obstruction?	Piping/STP Su					
Are Sumps Clean and free from water, debris, product etc?		Oyes	ØNo □ Mo	OperatorNotified	Yes	ONO	
A I IDCs alean and free from water, debris, product etc?		spenser Contain	No	OperatorNotified		Ovo	
NOTE: ALL LIQUID/DEBRIS OR WASTE MUST BE DISPOSSED OFF ACCORDING TO EXISTING RULES AND REQULATIONS FOLLOWING PROPER PROCEDUE BY A CERTIFIED CONTRACTOR.							
Operator on Duty Name			Signature			www.tanksdata.com	
317-645-0215	tai	nksdata@gmail.	com	1	w w w.tanas	20220516	