Tanks Data	3	0 DAYS V	VALK THROUGH	INSPE	CTION	
UST Facility I.D.((FID) # 18 719	Contact Nu	Contact Number				
Facility Name 13 P	Contact email					
Address 209 5 W State Rd 2046565	Date of Inspection $06-22-2025$					
Operator on Duty Name	Name of th	Name of the Person				
Or	perator Train	Inspection	Cruysrus			
Operator Training current	Yes	No	OperatorNotified	Yes	ONO	
Registra	tion/Notificat		Operatoritotis		<u> </u>	
Is Registration current with correct owner, operator etc.	Yes	No	OperatorNotified	Ves	010	
	elease Detecti				Other	
Release Detection Method	ATG	CIM	SIR	OIC	Other	
Make and Model / R 125-35	00					
Does it have paper?	Yes	No	OperatorNotified	Yes	240	
Is it in Alarm mode?	Yes	No	OperatorNotified		QNo	
Interstitial Monitoring Sensor Status Normal	Yes	No	OperatorNotified		ONO	
Necessary Monthly Printout Taken	Yes	No	OperatorNotified		Ovo	
	Spill Buckets					
Are Spill Buckets Clean and free from water, debris, product etc?	Ves	Ø No	OperatorNotified	es	010	
Are the Spill Bucket in good condition and free of damage/cracks	Yes	No	OperatorNotified	es	Olo	
	Fill Ports	9				
Is Fill pipe cap tight and fill pipe free from any obstruction?	Yes	No	OperatorNotified	Oes	ONO	
Pip	oing/STP Sun	nps				
Are Sumps Clean and free from water, debris, product etc?	Yes	(P)No	OperatorNotified	Ves	Olo	
Under Disper	nser Contain	ments (UDC)				
Are UDCs clean and free from water, debris, product etc?	Yes	ONO	OperatorNotified	Yes	Olo	
NOTE: ALL LIQUID/DEBRIS OR WASTE MUST BE DISPO FOLLOWING PROPER PRO	OSSED OFF A	ACCORDING CERTIFIED	TO EXISTING RULES. CONTRACTOR.			
Operator on Duty Name		Signature	1	Date 0	6-22-292	
	lata@gmail.com			www.tanksdata.com		
tanksa	ши обрания.				20220516	