Tanks Data	3	0 DAYS W	ALK THROUGH	INSPEC	CTION
UST Facility I.D.((FID) # a5131	Contact No	ımber			
Facility Name Marathon	Contact email				
Address 1149 N Main St Goshen 46528					
Operator on Duty Name	_		5/15/23	^ .	
The state of the s	Name of the Person Conducting Inspection Josh			Rider	
O	perator Train				
Operator Training current	Oyes	No	OperatorNotified	Yes	No
Registra	tion/Notifica	tion Form			0
Is Registration current with correct owner, operator etc.	Yes	\bigcirc Vo	OperatorNotified	()res	Olo
	elease Detect	on			
Release Detection Method	⊘ ATG	C IM	SIR	OIC	Other
Make and Model	Franklin	F5 TS-7	50		_
Does it have paper?	Yes	No	OperatorNotified	Yes	Olo
Is it in Alarm mode?	Yes	No	OperatorNotified	Yes	No
Interstitial Monitoring Sensor Status Normal	Yes	No	OperatorNotified	Ves	No
Necessary Monthly Printout Taken	Yes	No	OperatorNotified	Yes	No
	Spill Bucket			Ocs	0.0
Are Spill Buckets Clean and free from water, debris, product etc?	Ves	No	OperatorNotified	Oho	01-
Are the Spill Bucket in good condition and free of damage/cracks	Ves	No	OperatorNotified	X cs	X ₁₀
	Fill Ports	O.º	Operatorivotnieu	Oes	O _{NO}
Is Fill pipe cap tight and fill pipe free from any obstruction?	(Ves	No	OperatorNotified	Ores	Olo
	ping/STP Sur	nps		Ocs	ONO
Are Sumps Clean and free from water, debris, product etc?	Yes	No	OperatorNotified	OVes	Ola
Under Dispe	nser Contain	ments (UDC)		U CS	Cro
Are UDCs clean and free from water, debris, product etc?	Yes	(V)o	OperatorNotified	(Xes	Ola
NOTE: ALL LIQUID/DEBRIS OR WASTE MUST BE DISP FOLLOWING PROPER PRO	OSSED OFF CEDUE BY A	ACCORDING CERTIFIED	TO EVICTING DILLEG	AND REQU	LATIONS
perator on Duty Name		Signature		Date	
317-645-0215 tanksc	sdata@gmail.com			www.tanksdata.com	