Tanks Data				
UST Facility I.D.((FID) #	15156 2000	Contact Number		
Facility Name	Marcelhan	Contact email		
Address 114 9 N Main	w. St. Gorshow.	Date of Inspection		50-100 C
Operator on Duty Name	82594 NI	Name of the Person Conducting Inspection	1/10 Exx	AND -
		Operator Training		
Operator	Operator Training current	Ores One	OperatorNotified	Q _g
Is Registration current w	Registration current with correct owner, operator etc.	Registration/Notification Form	OperatorNotified	Oes Oo
Release D	Release Detection Method	WATE CIM		5
Make	Make and Model	700	3	Or Omer
Does it	Does it have paper?	Dires 1	Operator Notified	
Is it in A	Is it in Alarm mode?		OperatorNotified)(
Interstitial Monitori	Interstitial Monitoring Sensor Status Normal		Operator Notified	\mathcal{X}
Necessary Mor			OperatorNotified	
Are Spill Buckets Clean and f	Are Spill Buckets Clean and free from water, debris, product etc?	Ores XNo	OperatorNotified	3
Are the Spill Bucket in good c	Are the Spill Bucket in good condition and free of damage/cracks		OperatorNotified	
Is Fill pipe cap tight and fil	Is Fill pipe cap tight and fill pipe free from any obstruction?	Piping/STP Sumps	OperatorNotified	Oes Oto
Are Sumps Clean and free	Are Sumps Clean and free from water, debris, product etc? Under Disper	uct etc? Ofes Olo Under Dispenser Containments (UDC)	OperatorNotified	Os Os
Are UDCs clean and free	Are UDCs clean and free from water, debris, product etc?		OperatorNotified	5
NOTE: ALL LIQUIDA	NOTE: ALL LIQUIDIDEBRIS OR WASTE MUST BE DISPOSSED OFF ACCORDING TO EXISTING RULES AND REQULATIONS FOLLOWING PROPER PROCEDUE BY A CERTIFIED CONTRACTOR.	DISSED OFF ACCORDING TO CEDUE BY A CERTIFIED C	O EXISTING RULES A	ND REQUILATIONS
Operator on Duty Name		Signature		Date
317-645-0215	tanksd	tanksdata@gmail.com		www.tanksdata.com