

000
TANKS DATA

30 DAYS WALK THROUGH INSPECTION

UST Facility I.D. (FID) # 25131 Contact Number

Facility Name Marathon Contact email

Address 144 N Main St Coshocton OH 43828 Date of Inspection 1/25/24

Inspector on Duty Name Austin B. Name of the Person Conducting Inspection

Operator Training current ☒ Yes ☐ No Operator Notified ☐ Yes ☐ No

Is Registration current with correct owner, operator etc. ☐ Yes ☐ No Operator Notified ☐ Yes ☐ No

Release Detection Method ☒ MTC ☐ DIM ☐ SIR ☐ IC ☐ Other

Make and Model ETS TS-250 Operator Notified ☐ Yes ☐ No

Does it have paper? ☒ Yes ☐ No Operator Notified ☐ Yes ☐ No

Is it in Alarm mode? ☐ Yes ☒ No Operator Notified ☐ Yes ☐ No

Interstitial Monitoring Sensor Status Normal ☐ Yes ☒ No Operator Notified ☐ Yes ☐ No

Necessary Monthly Printout Taken ☒ Yes ☐ No Operator Notified ☐ Yes ☐ No

Spill Buckets Clean and free from water, debris, product etc? ☒ Yes ☐ No Operator Notified ☐ Yes ☐ No

Is the Spill Bucket in good condition and free of damage/cracks ☒ Yes ☐ No Operator Notified ☐ Yes ☐ No

Is Fill pipe cap tight and fill pipe free from any obstruction? ☒ Yes ☐ No Operator Notified ☐ Yes ☐ No

Fill Ports ☒ Yes ☐ No Operator Notified ☐ Yes ☐ No

Are Sumps Clean and free from water, debris, product etc? ☒ Yes ☐ No Operator Notified ☐ Yes ☐ No

Piping/STP Sumps ☒ Yes ☐ No Operator Notified ☐ Yes ☐ No

Are UDCs clean and free from water, debris, product etc? ☒ Yes ☐ No Operator Notified ☐ Yes ☐ No

NOTE: ALL LIQUID/DEBRIS OR WASTE MUST BE DISPOSED OFF ACCORDING TO EXISTING RULES AND REGULATIONS FOLLOWING PROPER PROCEDURE BY A CERTIFIED CONTRACTOR.

Operator on Duty Name Signature Date

317-645-0215 tanksdata@gmail.com www.tanksdata.com