Tanks Data	30 DAYS WALK THROUGH INSPECTION
IST Facility I.D.((FLD)# 2,51 31	Contact Number
acility Name /49/64/601	Contact email
Address 1 49 N Main 2 1465 22	Date of Inspection 69-7 2-7575
Operator on Duty Name	Name of the Person Conducting Inspection Surpres
Op	erator Training
Operator Training current	OYes (No OperatorNotified Yes (No
Registrat	ion/Notification Form
Is Registration current with correct owner, operator etc.	OYes No OperatorNotified Yes No
	lease Detection
Release Detection Method	OATG CIM SIR OIC Other
Make and Model 15-t & L	Ly Eliny
Does it have paper?	Yes No OperatorNotified Yes No
Is it in Alarm mode?	Yes No OperatorNotified Yes No
Interstitial Monitoring Sensor Status Normal	Yes No OperatorNotified Yes No
Necessary Monthly Printout Taken	Yes No OperatorNotified Yes No
	Spill Buckets
Are Spill Buckets Clean and free from water, debris, product etc?	Ores No Operator Notified Ses No
Are the Spill Bucket in good condition and free of damage/cracks	Yes No OperatorNotified Ses No
	FNI Ports
Is Fill pipe cap tight and fill pipe free from any obstruction?	Yes No OperatorNotified Jes No
Pij	ping/STP Sumps
Are Sumps Clean and free from water, debris, product etc?	Ores No OperatorNotified Ores No
Under Dispe	enser Containments (UDC)
Are UDCs clean and free from water, debris, product etc?	Ores (No OperatorNotified (Yes (No
NOTE: ALL LIQUID/DEBRIS OR WASTE MUST BE DISP FOLLOWING PROPER PRO	OSSED OFF ACCORDING TO EXISTING RULES AND REQULATIONS OCEDUE BY A CERTIFIED CONTRACTOR.
perator on Duty Name	Signature
317-645-0215 tankso	data@gmail.com www.tanksdata.com
LUITINO	21