30 DAYS WALK THROUGH INSPECTI					TION		
Tanks Data		-					
ST Facility I.D.((FID)# 2513		Contact Nun	Contact Number				
acility Name Marathon		Contact ema	Contact email				
ddress 1149 N Main (44652)		Date of Inspe	Date of Inspection $02-28-2025$				
perator on Duty Name			Name of the Person Conducting Inspection Curlself				
		Operator Trainin	ng				
Operato	or Training current	Yes	ONo	OperatorNotified	Yes	(No	
		ration/Notificati	on Form		_		
Is Registration current	with correct owner, operator etc.	Yes	ONO	OperatorNotified	Ores	Oio	
		Release Detection	n				
Release Detection Method		ATG	CIM	SIR	OIC	Other	
	ake and Model +5 -750	Tarksentin	9				
Does it have paper?		Yes	ONo	OperatorNotified	Yes	Oio	
Is it in Alarm mode?		Yes	No	OperatorNotified	Yes	Olo	
Interstitial Monitoring Sensor Status Normal		Yes	No	OperatorNotified	Yes	No	
Necessary Monthly Printout Taken		Yes	No	OperatorNotified	Yes	No	
		Spill Buckets			_		
Are Spill Buckets Clean a	nd free from water, debris, product et	Control of the Contro	ONO	OperatorNotified	@ Yes	Ovo	
Are the Spill Bucket in good condition and free of damage/cracks		and the state of t	No	OperatorNotified	Ces	No	
		Fill Ports					
Is Fill pipe cap tight an	d fill pipe free from any obstruction?	Yes	ONO	OperatorNotified	Oes	Olo	
		Piping/STP Sur	nps		~		
Are Sumps Clean and	d free from water, debris, product etc?	Yes	Ø10	OperatorNotified	W res	Olo	
		ispenser Contair	ments (UDC)				
Are UDCs clean and free from water, debris, product etc?		Yes	€ No	OperatorNotified	(V) res	Olo	
NOTE: ALL LIQU	JID/DEBRIS OR WASTE MUST BE D FOLLOWING PROPER I				AND REQU	LATIONS	
Operator on Duty Name			Signature		Date		
317-645-0215	ta	tanksdata@gmail.com				www.tanksdata.com	