

NORTH MEADOW C-STOR
1149 N. MAIN ST.
GSHEN IN 45628
574-975-0391

05/28/2025

3:05 PM

REGULATORY REPORT

HARDWARE STATUS

TS-CIM	NOT INSTALLED
TS-RDM	NOT INSTALLED
TS-SEM 1	NOT INSTALLED
TS-SEM 2	NOT INSTALLED
TS-CPM	NOT INSTALLED
PRINTER	OPERATIONAL
FAX/MOD	OPERATIONAL

PROBES

PROBE 1	OPERATIONAL
PROBE 2	OPERATIONAL
PROBE 3	OPERATIONAL

AUXILIARY INPUTS

AUX IN 1	OPERATIONAL
AUX IN 2	OPERATIONAL

PASSED LEAK TESTS

	TANK 1	
02/24/2019		6:09 AM
LEAK TEST		0.20 GPH
SLOPE		-0.07 GPH

	TANK 2	
09/08/2019		2:50 AM
LEAK TEST		0.20 GPH
SLOPE		-0.02 GPH

	TANK 3	
09/08/2019		4:09 AM
LEAK TEST		0.20 GPH
SLOPE		0.01 GPH

PASSED SCALD TESTS

	TANK 1	
05/28/2025		3:38 AM
LEAK TEST		0.20 GPH
SLOPE		-0.09 GPH

03/30/2031		12:55 AM
LEAK TEST		0.20 GPH
SLOPE		-0.06 GPH

02/28/2031		4:02 AM
LEAK TEST		0.20 GPH
SLOPE		-0.05 GPH

02/03/2021		10:58 PM
LEAK TEST		0.20 GPH
SLOPE		-0.06 GPH

	TANK 2	
05/28/2025		6:29 AM
LEAK TEST		0.20 GPH
SLOPE		0.01 GPH

04/18/2031		11:47 PM
LEAK TEST		0.20 GPH
SLOPE		0.04 GPH

03/19/2031		10:18 PM
LEAK TEST		0.20 GPH
SLOPE		0.02 GPH

02/17/2031		12:07 AM
LEAK TEST		0.20 GPH
SLOPE		0.02 GPH

02/16/2021		4:50 AM
LEAK TEST		0.20 GPH
SLOPE		-0.09 GPH

	TANK 3	
05/28/2025		11:00 AM
LEAK TEST		0.20 GPH
SLOPE		-0.05 GPH

04/17/2031		10:45 PM
LEAK TEST		0.20 GPH
SLOPE		0.01 GPH

03/18/2031		11:37 PM
LEAK TEST		0.20 GPH
SLOPE		0.03 GPH

02/16/2031		11:16 AM
LEAK TEST		0.20 GPH
SLOPE		0.00 GPH

02/16/2021		9:18 AM
LEAK TEST		0.20 GPH
SLOPE		0.02 GPH