

NORTH MEADOW C-STOR
1149 N. MAIN ST.
GOSHEN IN 45628
574-975-0391

06/30/2025

5:20 PM

REGULATORY REPORT

HARDWARE STATUS

TS-CTM	NOT INSTALLED
TS-RDM	NOT INSTALLED
TS-SEM 1	NOT INSTALLED
TS-SEM 2	NOT INSTALLED
TS-CPM	NOT INSTALLED
PRINTER	OPERATIONAL
FAX/MOD	OPERATIONAL

PROBES

PROBE 1	OPERATIONAL
PROBE 2	OPERATIONAL
PROBE 3	OPERATIONAL

AUXILIARY INPUTS

AUX IN 1	OPERATIONAL
AUX IN 2	OPERATIONAL

PASSED LEAK TESTS

TANK 1

02/24/2019	6:09 AM
LEAK TEST	0.20 GPH
SLOPE	-0.07 GPH

TANK 2

09/08/2019	2:50 AM
LEAK TEST	0.20 GPH
SLOPE	-0.02 GPH

TANK 3

09/08/2019	4:09 AM
LEAK TEST	0.20 GPH
SLOPE	0.01 GPH

PASSED SCALD TESTS

TANK 1

06/21/2025	12:00 AM
LEAK TEST	0.20 GPH
SLOPE	0.05 GPH

03/30/2031	12:55 AM
LEAK TEST	0.20 GPH
SLOPE	-0.06 GPH

02/28/2031	4:02 AM
LEAK TEST	0.20 GPH
SLOPE	-0.05 GPH

02/03/2021	10:58 PM
LEAK TEST	0.20 GPH
SLOPE	-0.06 GPH

TANK 2

06/30/2025	2:18 AM
LEAK TEST	0.20 GPH
SLOPE	0.04 GPH

04/18/2031	11:47 PM
LEAK TEST	0.20 GPH
SLOPE	0.04 GPH

03/19/2031	10:18 PM
LEAK TEST	0.20 GPH
SLOPE	0.02 GPH

02/17/2031	12:07 AM
LEAK TEST	0.20 GPH
SLOPE	0.02 GPH

02/16/2021	4:50 AM
LEAK TEST	0.20 GPH
SLOPE	-0.09 GPH

TANK 3

06/30/2025	3:24 PM
LEAK TEST	0.20 GPH
SLOPE	-0.04 GPH

04/17/2031	10:45 PM
LEAK TEST	0.20 GPH
SLOPE	0.01 GPH

03/18/2031	11:37 PM
LEAK TEST	0.20 GPH
SLOPE	0.03 GPH

02/16/2031	11:16 AM
LEAK TEST	0.20 GPH
SLOPE	0.00 GPH

02/16/2021	9:18 AM
LEAK TEST	0.20 GPH
SLOPE	0.02 GPH