Tanks Data	3	30 DAYS V	VALK THROUGE	INSPE	CTION
UST Facility I.D.((FID) # 2513/	Contact N	Contact Number			
Facility Name Magreethon		Contact email			
Address 1149 N Min 5 + 5004 4657	Date of Ins	Date of Inspection 06-30-2025			
Operator on Duty Name	Name of the	ne Person g Inspection	Georgerest		
Operator Training current	Operator Train	No	OperatorNotified	OYes	ONo
Regis Is Registration current with correct owner, operator etc.	tration/Notification	tion Form	OperatorNotified	Ores	Oto
Release Detection Method	Release Detection	OIM	SIR	OIC	Other
Make and Model 75-750 TA	7NKSEN GYes	TINEN	TA L OperatorNotified	OYes	O40
Does it have paper? Is it in Alarm mode?	Yes	Ø\v∘	OperatorNotified	Yes	810
Interstitial Monitoring Sensor Status Normal Necessary Monthly Printout Taken	Yes	S _{No}	OperatorNotified OperatorNotified	O'es	010
	Spill Bucket	s			0.
Are Spill Buckets Clean and free from water, debris, product etc. Are the Spill Bucket in good condition and free of damage/crack	c? Ores	No No	OperatorNotified OperatorNotified	es es	8.0
Is Fill pipe cap tight and fill pipe free from any obstruction?	Fill Ports	O ₁₀	OperatorNotified	Oes	O40
Are Sumps Clean and free from water, debris, product etc?	Piping/STP Sur Yes	nps (P)Vo	OperatorNotified	Yes	Oıo
Under Die	spenser Contain	ments (UDC)	OperatorNotified	Ø Yes	(No
Are UDCs clean and free from water, debris, product etc? NOTE: ALL LIQUID/DEBRIS OR WASTE MUST BE DIA NOTE: ALL LIQUID/DEBRIS OF WASTE BE DIA NOTE: ALL LI	SPOSSED OFF	ACCORDING	TO EXISTING RULES	AND REQU	
FOLLOWING PROPERTY	KOCEDOE DI A	Signature		Date 06	
Operator on Duty Name 317-645-0215 tan	ksdata@gmail.co	om graf	ned	www.tanks	