

30 DAYS WALK THROUGH INSPECTION

all

Tank Data

UST Facility I.D. (FID) # 15500

Contact Number

Facility Name M0812

Contact email

Address 750 CR Road 15, Sikest, IN

Date of Inspection 06/09/24

Operator on Duty Name

Name of the Person Conducting Inspection AKSMT SPARRAN

Operator Training current

Operator Training ☒ Yes ☐ No Operator Notified ☐ Yes ☐ No

Is Registration current with correct owner, operator etc.

Registration/Notification Form ☐ Yes ☐ No Operator Notified ☐ Yes ☐ No

Release Detection Method

Release Detection ☒ ATG ☐ TIM ☐ BIR ☐ IC ☐ Other

Make and Model

Does it have paper?

Is it in Alarm mode?

Interstitial Monitoring Sensor Status Normal

Necessary Monthly Printout Taken

Spill Buckets

Spill Buckets ☒ Yes ☐ No Operator Notified ☐ Yes ☐ No

Are Spill Buckets Clean and free from water, debris, product etc?

Are Spill Buckets in good condition and free of damage/cracks ☒ Yes ☐ No Operator Notified ☐ Yes ☐ No

Is Fill pipe cap tight and fill pipe free from any obstruction?

Fill Ports ☒ Yes ☐ No Operator Notified ☐ Yes ☐ No

Are Sumps Clean and free from water, debris, product etc?

Piping/STP Sumps ☒ Yes ☐ No Operator Notified ☐ Yes ☐ No

Are UDCs clean and free from water, debris, product etc?

Under Dispenser Containments (UDC) ☒ Yes ☐ No Operator Notified ☐ Yes ☐ No

NOTE: ALL LIQUID/DEBRIS OR WASTE MUST BE DISPOSED OFF ACCORDING TO EXISTING RULES AND REGULATIONS FOLLOWING PROPER PROCEDURE BY A CERTIFIED CONTRACTOR.

Operator on Duty Name

Signature

Date

317-645-0215

tankdata@gmail.com

www.tankdata.com

20220516