Tanks Data	30 DAYS WALK THROUGH INSPECTION					
UST Facility I.D.((FID) # 15500	Contact Number					
Facility Name Mobil	Contact email					
Address 750 CR-15 ElKhart 46516	Date of Inspection 2/2/24					
Operator on Duty Name	Name of the Person Conducting Inspection Josh R			der		
	erator Train	ing				
Operator Training current	Yes	○No	OperatorNotified	Yes	ON ₀	
Registra	tion/Notificat	ion Form		_		
Is Registration current with correct owner, operator etc.	Yes	\bigcirc Vo	OperatorNotified	Ves	Olo	
	elease Detecti	on			-	
Release Detection Method	√ ATG	C IM	SIR	OIC	Other	
Make and Model	VR	TLS-450	Plus	•	_	
Does it have paper?	Yes	ON ₀	OperatorNotified	Yes	Olo	
Is it in Alarm mode?	(V)Yes	No	OperatorNotified	Yes	Olo	
Interstitial Monitoring Sensor Status Normal	Yes	No	OperatorNotified	Yes	No	
Necessary Monthly Printout Taken	Yes	No	Operator Notified	Yes	No	
	Spill Bucket	s		O	O.º	
Are Spill Buckets Clean and free from water, debris, product etc?	Yes	Mominima	Operator Notified	Chas	Ota	
Are the Spill Bucket in good condition and free of damage/cracks	Ves	No	Operator Notified	es	\searrow	
	Fill Ports	0	o peracorriotine	Os	O ₁₀	
Is Fill pipe cap tight and fill pipe free from any obstruction?	(Ves	No	OperatorNotified	Ces	Ola	
Pi	ping/STP Sur	nps_minima	the first transfer of the second seco	Ocs	ONO.	
Are Sumps Clean and free from water, debris, product etc?	Oyes	(V)Vo	Operator Notified	(Ves	Ola	
Under Dispe	nser Contain	ments (UDC)		V ICS	CNO	
Are UDCs clean and free from water, debris, product etc?	Wes	(A)Io	OperatorNotified	OVac	0	
NOTE: ALL LIQUID/DEBRIS OR WASTE MUST BE DISP FOLLOWING PROPER PRO	OSSED OFF	ACCORDING T	O EVICENIC PART	AND REQU	LATIONS	
Operator on Duty Name		Signature	ONTRACTOR.	-		
217 645 0215				Date		
tanksdata@gmail.com			m		www.tanksdata.com	