Tanks Data	3	0 DAYS W	ALK THROUGH	INSPEC	TION
UST Facility I.D.((FID) # 15560	Contact Number				
Facility Name 105tl	Contact email				
Address 750 CR 2000 15 41516	Date of Inspection 06-26-2025				
Operator on Duty Name	Name of the Person Conducting Inspection Turkroat				
01	perator Train		1		
Operator Training current	Yes	ONo	OperatorNotified	Yes	(No
Registra	tion/Notifica	tion Form			
Is Registration current with correct owner, operator etc.	Yes	ONo	OperatorNotified	()Yes	Oio
	elease Detect	~		O	
Release Detection Method	ATG	(JEIM	SIR	OIC	Other
Make and Model VKTLS 3	5010	13		<u> </u>	
Does it have paper?	Yes	QN ₀	OperatorNotified	Yes	No.
Is it in Alarm mode?	Yes	QNo	OperatorNotified	Yes	\bigcirc No
Interstitial Monitoring Sensor Status Normal	Yes	ON0	OperatorNotified	Yes	QN0
Necessary Monthly Printout Taken	Yes	ONO	OperatorNotified	O'es	Olo
	Spill Bucket	S			
Are Spill Buckets Clean and free from water, debris, product etc?	Yes	ONO	OperatorNotified	Oes	Olo
Are the Spill Bucket in good condition and free of damage/cracks	Fill Ports	O _N o	OperatorNotified	Oes	O40
Is Fill pipe cap tight and fill pipe free from any obstruction?	Yes	No	OperatorNotified	Oes	Olo
	ping/STP Su	mps			
Are Sumps Clean and free from water, debris, product etc?	Yes	Olo	OperatorNotified	Ores	Olo
Under Dispe	enser Contain	ments (UDC)			
Are UDCs clean and free from water, debris, product etc?	Yes	ONo	OperatorNotified	Ores	Olo
NOTE: ALL LIQUID/DEBRIS OR WASTE MUST BE DISP FOLLOWING PROPER PRO	OSSED OFF	ACCORDING 4 CERTIFIED	TO EXISTING RULES CONTRACTOR.	AND REQU	JLATIONS
Operator on Duty Name		Signature		Date 5	1-26-202
	data@gmail.c	om Gurb	300	www.tanks	