

UST TESTING/INSPECTION RESULTS SUMMARY

OWNER NAME: Tanks Data OWNER ADDRESS: 1245 South Main Street OWNER CITY/STATE/ZIP: Elkhart, IN 46516

> TESTING DATE: 8/29/2023

LOCATION NAME: Citgo Elkhart **LOCATION ADDRESS:** 1245 South Main Street LOCATION CITY/STATE: Elkhart, IN 46516 LOCATION FID#:

METHOD OF TANK LEAK DETECTION METHOD OF PIPING LEAK DETECTION PRESSURE TYPE OF UNDERGROUND PIPING STEEL

ANNUAL TESTING/INSPECTIONS

AUTOMATIC TANK GAUGE TEST

COMPLETED

TANK NO	PRODUCT	BRAND/MODEL	RESULT
1	RUL	INCON	PASS
2	DSL	INCON	PASS
3	PUL	INCON	FAIL

EAI	C DETECTOR TEST	r	COMPLETED	
ĺ	LINE NO	PRODUCT	TYPE	RESULT
ĺ	1	RUL	MLLD	PASS
	2	DSL	MLLD	PASS
ſ	3	PUL	MLLD	PASS
ſ				

PRODUCT LINE TEST

COMPLETED

Product line must b			
LINE NO	PRODUCT	RESULT	AMT OF CHG/GPH
1	RUL	PASS	0
2	DSL	PASS	0
3	PUL	PASS	0
		l	l

LIQU	JID SENSOR FUNC	CTIONALITY TEST	NOT PERFORMED	
	LOCATION	PRODUCT	TYPE	RESULT

LEGEND:

RUL	Regular Unleaded
DSL	Diesel
PUL	Premium Unleaded
KER	Kerosene
ODSL	Off Road Diesel
REC	Recreational



SITE PHOTOS


TEST DATE: 8/29/2023		
LOCATION NAME:	Citgo Elkhart	
LOCATION ADDRESS:	1245 South Main Street	
LOCATION CITY/STATE:	Elkhart, IN 46516	
LOCATION PHONE:	0	
LOCATION CONTACT: Virendar Kumar		

OWNER NAME: Tanks Data OWNER ADDRESS: 1245 South Main Street OWNER CITY/STATE/ZIP: Elkhart, IN 46516 LOCATION FID#: 01633 WORK ORDER NO: NE-0543

DSL ATG PROBE TEST



RUL ATG PROBE TEST





CERTIFICATION VERIFICATION

0

Tanks Data 1245 South Main Street Elkhart, IN 46516

Testing Date: 8/29/2023

Citgo Elkhart

Location of Test: 1245 South Main Street Elkhart, IN 46516

Site FID#: 01633

Service Technican:

Certified Technician: RONNIE BROWN


Midwest ECS has completed the following tests/inspections at the above noted location:

ATG Functionality	Х
Leak Detector	Х
Elec Line Leak Detector	
Product Line Testing	Х
Liquid Sensor Functionality	
Spill Bucket	
Containment Hydrostatic Sump	
Overfill Equipment Inspection	
Overfill Alarm	
Vent Valve	
Interstital	
Non-Volumetric Tank Tightness	
Shear Valve Inspection	

I, RONNIE BROWN , the certified technician, was present throughout the duration of the testing and/or inspection performed by Midwest ECS at the above address on the above date. I affirm that the testing was done in accordance with Rule 329 IAC 9 and 40CFR Part 80, is accurate based upon the results received and that these forms accurately reflects the results of the testing and/or inspection.

 Technician Signature:
 RONNIE BROWN

 Date & Time:
 8/29/2023 12:00



I attest with my signature below, that this technician was present onsite for testing as described above.