Tanks Data	30 DAYS WALK THROUGH INSPECTION				
ST Facility I.D.( (FID) # 24944	Contact Number				
acility Name Phillips 66	Contact email				
ddress 720 S Van Buren St Shipshewana	Date of Inspection 5/5/23				
perator on Duty Name 46565	27 01 7			sh Rider	
Op	erator Train				
Operator Training current	Yes	ON <sub>o</sub>	OperatorNotified	Yes	ON <sub>0</sub>
Registrat	ion/Notificat	tion Form		_	_
Is Registration current with correct owner, operator etc.	Yes	O <sub>N</sub> o	OperatorNotified	Yes	Olo
	lease Detecti	~	_		_
Release Detection Method	ATG	<b>CEIM</b>	SIR	Orc	Other
Make and Model	VR	TLS-3	50		_
Does it have paper?	Yes	O <sub>10</sub>	OperatorNotified	Yes	Oto
Is it in Alarm mode?	Yes	O <sub>No</sub>	OperatorNotified	Ves	Olo
Interstitial Monitoring Sensor Status Normal	Yes	O <sub>No</sub>	OperatorNotified	Yes	Olo
Necessary Monthly Printout Taken	Yes	No	OperatorNotified	Yes	No
	Spill Bucket	3		0	
Are Spill Buckets Clean and free from water, debris, product etc?	Yes	(VNo	OperatorNotified	(V)es	No
Are the Spill Bucket in good condition and free of damage/cracks	(V)Yes	No	OperatorNotified	es	No
	Fill Ports	0			0.
Is Fill pipe cap tight and fill pipe free from any obstruction?	Yes	O₁₀	<b>OperatorNotified</b>	Tes	OYO
	ping/STP Su	mps		_	
Are Sumps Clean and free from water, debris, product etc?	Yes	Ø⁄40	OperatorNotified	Yes	No
	enser Contai	nments (UDC)			
Are UDCs clean and free from water, debris, product etc?	Yes	Ø/o	OperatorNotified	(V)res	Olo
NOTE: ALL LIQUID/DEBRIS OR WASTE MUST BE DISP FOLLOWING PROPER PRO	POSSED OFF OCEDUE BY	ACCORDING A CERTIFIED	TO EXISTING RULES CONTRACTOR.	AND REQU	LATIONS
Operator on Duty Name		Signature		Date	
317-645-0215 tanks	data@gmail.com			www.tanksdata.com	