	30 DAYS WAL	30 DAYS WALK THROUGH INSPECTION	SPECTION
UST Facility I.D.(FID)# 241144	Contact Number		
	Contact email		
Address 720 S Van buren st	Date of Inspection スースノースレ	Y	
Operator on Duty Name	Name of the Person	Stin B.	
Operator Training current	Operator Training Oyes ONo	OperatorNotified ()res Ovo
Registration current with correct owner, operator etc.	Form	OperatorNotified (Ocs Ovo
Release Detection Method	ATG DIM		Tic Other
Make and Model	7(
Does it have paper?	Oxes Oxo	OperatorNotified (Yes Quo
Is it in Alarm mode?	Okes Okes	OperatorNotified () fee
Interstitial Monitoring Sensor Status Normal		Operator Notified	
Necessary Monthly Printout Taken	Spill Buckets M. A. A.	OperatorNotified	0
Are Spill Buckets Clean and free from water, debris, product etc? Are the Spill Bucket in good condition and free of damage/cracks	Fill Ports	OperatorNotified OperatorNotified	Š Š Š
Is Fill pipe cap tight and fill pipe free from any obstruction? I	Oves Ovo	OperatorNotified	Oes Qio
Are Sumps Clean and free from water, debris, product etc? Under Dis	ot etc?	OperatorNotified	Ores Oro
Are UDCs clean and free from water, debris, product etc?	Oxes Quo	OperatorNotified	Oes Olo
NOTE: ALL LIQUID/DEBRIS OR WASTE MUST BE DISPOSSED OFF ACCORDING TO EXISTING FOLLOWING PROPER PROCEDUE BY A CERTIFIED CONTRACTOR	FOR WASTE MUST BE DISPOSSED OFF ACCORDING TO EXISTING I	TO EXISTING RULES CONTRACTOR.	QULATION
Operator on Duty Name	Signature		Date
317-645-0215 tan	tanksdata@gmail.com		www.tanksdata.com