Tanks Data	30 DAYS W	ALKTHROUGH	INSPEC	TION
ST Facility I.D.((FID)# 2444	Contact Number			
acility Name Willes	Contact email			
address 770 SUMA 10 ROLET	Date of Inspection	9-72-	200	55
Operator on Duty Name 46869		Gu		
Op	erator Training			
Operator Training current	OYes ONo	OperatorNotified	OY'es	(No
Is Registration current with correct owner, operator etc.	Yes No	OperatorNotified	Ores	010
Release Detection Method Make and Model	elease Detection	OSIR	Oic	Other
Does it have paper?	Wes No	OperatorNotified	Yes	Olo
Is it in Alarm mode?	Oves ONo	OperatorNotified	Yes	Olo
Interstitial Monitoring Sensor Status Normal	Xes No	OperatorNotified	Yes	No
Necessary Monthly Printout Taken	Yes ONo Spill Buckets	OperatorNotified	Ores	010
Are Spill Buckets Clean and free from water, debris, product etc?	Ores No	OperatorNotified	Oos	Olo
Are the Spill Bucket in good condition and free of damage/cracks	Fill Ports	OperatorNotified	Oes	010
Is Fill pipe cap tight and fill pipe free from any obstruction?	Ores ONO ping/STP Sumps	OperatorNotified	Oes	Oio
Are Sumps Clean and free from water, debris, product etc?	Ores No enser Containments (UDC)	OperatorNotified	Ores	010
Are UDCs clean and free from water, debris, product etc?	0.	그는 이번 살아보고 아름답다. 남동하다 사용하다	00	
NOTE: ALL LIQUID/DEBRIS OR WASTE MUST BE DISP FOLLOWING PROPER PRO	OSSED OFF ACCORDING	Operator Notified TO EXISTING RULES	AND REQU	LATIONS
Operator on Duty Name	Signature	CONTRACTOR.	Dete	
317-645-0215 tanks	data@gmail.com		Date	
lanks	data (e.g. gillali.COIII	\	www.tanksc	lata.com