Tanks Data	30 DAYS WALK THROUGH INSPECTION				
JST Facility I.D.((FID) # 9063	Contact Number				
acility Name Marathon	Contact email				
Address 51452 SR-19 E1Khart 46514	Date of Inspection 7/19/a			3	
perator on Duty Name				Rider	
O	perator Train				
Operator Training current	Oyes	ON _o	OperatorNotified	Yes	ONo
Registra	tion/Notificat	ion Form		~	_
Is Registration current with correct owner, operator etc.	Yes	O_{i0}	OperatorNotified	Ves	Oto
	elease Detecti				_
Release Detection Method	⊘ ATG	CIM	O SIR	Oic	Other
Make and Model	VR	TLS-35	0		
Does it have paper?	Yes	O_{N_0}	OperatorNotified	Yes	Oto
Is it in Alarm mode?	Yes	(V)No	OperatorNotified	Yes	Olo
Interstitial Monitoring Sensor Status Normal	Yes	No	OperatorNotified	Yes	Ovo
Necessary Monthly Printout Taken	Yes	No	OperatorNotified	Yes	ONO
	Spill Bucket		.1 .4		
Are Spill Buckets Clean and free from water, debris, product etc?	Yes	No	nal water OperatorNotified	(Ves	Olo
Are the Spill Bucket in good condition and free of damage/cracks	Ves	No	OperatorNotified	Ces	No
	Fill Ports	0		0	0
Is Fill pipe cap tight and fill pipe free from any obstruction?	(Ves	\bigcirc No	OperatorNotified	() es	Olo
	ping/STP Sur	nps		_	_
Are Sumps Clean and free from water, debris, product etc?	O Yes	⊘ √o	OperatorNotified	Ves	No
Under Dispe	enser Contain	ments (UDC)			
Are UDCs clean and free from water, debris, product etc?	Yes	No	OperatorNotified	(V)res	No
NOTE: ALL LIQUID/DEBRIS OR WASTE MUST BE DISP FOLLOWING PROPER PRO	OSSED OFF . OCEDUE BY A	ACCORDING CERTIFIED	TO EXISTING RULES. CONTRACTOR.	AND REQU	LATIONS
Operator on Duty Name		Signature		Date	
317-645-0215 tanks	sdata@gmail.com			www.tanksdata.com	