Tanks Data	3	0 DAYS W	ALK THROUGH	INSPE	CTION
UST Facility I.D.((FID)#   6 5 6 9	Contact Number				
Facility Name Marathan	Contact email				
Address IIE Ireland 96019	Date of Inspection $07-29-7028$				
Operator on Duty Name	Name of the Person Conducting Inspection  Conducting Inspection				
Op	erator Train	ing			
Operator Training current	Yes	ONo	OperatorNotified	Yes	ONo
마셨다. () : [1] [1] [1] [2] [2] [2] [2] [2] [2] [2] [2] [2] [2	ion/Notificat	tion Form			
Is Registration current with correct owner, operator etc.	Yes	₩ <sub>0</sub>	OperatorNotified	Ves	Oio
	lease Detecti		O	0.0	
Release Detection Method	ATG	CIM	SIR	Oic	Other
Make and Model URTCS-3	50	O.		<u> </u>	
Does it have paper?	Yes	QNo.	OperatorNotified	Yes	Q10
Is it in Alarm mode?	(X)Yes	ON <sub>0</sub>	OperatorNotified	Yes	QVo
Interstitial Monitoring Sensor Status Normal	Yes	ONO	OperatorNotified	Yes	Oyo
Necessary Monthly Printout Taken	Yes	No	OperatorNotified	Tes	Olo
	Spill Bucket	s			
Are Spill Buckets Clean and free from water, debris, product etc?	Ves	(B)No	OperatorNotified	(V)es	Olo
Are the Spill Bucket in good condition and free of damage/cracks	Yes	No	OperatorNotified	es	Olo
	Fill Ports				_
Is Fill pipe cap tight and fill pipe free from any obstruction?	Yes	O <sub>N</sub> o	OperatorNotified	Oes	Oto
The state of the s	ping/STP Su	mps			
Are Sumps Clean and free from water, debris, product etc?	Yes	(D)10	OperatorNotified	Vres	Olo
Under Dispe	nser Contai	nments (UDC)	)		
Are UDCs clean and free from water, debris, product etc?	Yes	€No	OperatorNotified	(N) res	Olo
NOTE: ALL LIQUID/DEBRIS OR WASTE MUST BE DISP FOLLOWING PROPER PRO	OSSED OFF CEDUE BY	ACCORDING A CERTIFIED	TO EXISTING RULES CONTRACTOR.	AND REQU	ULATIONS
Operator on Duty Name		Signature		Date	17-29-70
[ - 18	data@gmail.d	com		www.tank	sdata.com 2022051