Tanks Data	30 DAYS WALK THROUGH INSPECTION				
JST Facility I.D.((FID) # 19871	Contact Number				
acility Name BP	Contact email				
Address 53031 SR-13 Middlebury 46540	Date of Inspection 1/2/24				
Decrator on Duty Name	Name of the Person Conducting Inspection Josh Rice			der	
O _I	perator Train	ing			
Operator Training current	Yes	○No	OperatorNotified	Yes	ONo
	tion/Notifica	tion Form		_	_
Is Registration current with correct owner, operator etc.	Yes	Û\o	OperatorNotified	Ves	Olo
	elease Detect			O	<u> </u>
Release Detection Method	⊘ ATG	CIM	SIR	Oic	Other
Make and Model	VR	TLS - 35		_	
Does it have paper?	Yes	O _N o	OperatorNotified	Yes	O10
Is it in Alarm mode?	Yes	No	OperatorNotified	OYes .	Olo
Interstitial Monitoring Sensor Status Normal	(V)/es	No	OperatorNotified	Yes	Olo
Necessary Monthly Printout Taken	Yes	No	OperatorNotified	O'res	Olo
	Spill Bucket	s	.1		
Are Spill Buckets Clean and free from water, debris, product etc?	Yes	s minima	OperatorNotified	(V)es	No
Are the Spill Bucket in good condition and free of damage/cracks	(V)Yes	No	OperatorNotified	es	No
	Fill Ports	0			
Is Fill pipe cap tight and fill pipe free from any obstruction?	Yes	Olo	OperatorNotified	Ces	Olo
	ping/STP Su			_	
Are Sumps Clean and free from water, debris, product etc?	Yes	\bigcirc I^{o}	Operator Notified	(√Yes	Olo
•	enser Contai	nments (UDC)			_
Are UDCs clean and free from water, debris, product etc?	Yes	\bigcirc No	OperatorNotified	Yes	Olo
NOTE: ALL LIQUID/DEBRIS OR WASTE MUST BE DISP FOLLOWING PROPER PRO	POSSED OFF OCEDUE BY	ACCORDING A CERTIFIED	TO EXISTING RULES CONTRACTOR.	AND REQU	LATIONS
Operator on Duty Name		Signature		Date	
	nksdata@gmail.com			www.tanksdata.com	