Tarks Data	30 DAYS WALK THROUGH INSPECTION
ST Facility I.D.((FID)# 19 \$77	Contact Number
acility Name BP	Contact email
Address 530315 R 13 46540	Date of Inspection $D2-19-7025$
Operator on Duty Name	Name of the Person Conducting Inspection Gurbreet
Operator Training current	OYes ONO OperatorNotified OYes ONO
Is Registration current with correct owner, operator etc.	On/Notification Form Oyes On OperatorNotified Ores Own lease Detection
Release Detection Method Make and Model UR TCS —) 5	OATG OIM OIC Other
Does it have paper? Is it in Alarm mode? Interstitial Monitoring Sensor Status Normal Necessary Monthly Printout Taken	Oversity of the control of the contr
Are Spill Buckets Clean and free from water, debris, product etc? Are the Spill Bucket in good condition and free of damage/cracks	Spill Buckets
Is Fill pipe cap tight and fill pipe free from any obstruction? Are Sumps Clean and free from water, debris, product etc?	O'es No OperatorNotified Oes No
Are UDCs clean and free from water debain	OYes Olo OperatorNotified Oyes Olo
NOTE: ALL LIQUID/DEBRIS OR WASTE MUST BE DIST	OYes ONO OperatorNotified Oes ONO OSSED OFF ACCORDING TO EXISTING RULES AND REQULATIONS OCEDUE BY A CERTIFIED CONTRACTOR.
317-645-0215	Signature Date 07-19-7075