Tanks Data	3	30 DAYS W	ALK THROUGH	INSPE	CTION
UST Facility I.D.((FID) # 19 771	Contact Number				
Facility Name	Contact email				
Address 530315R1341540	Date of Inspection 06 - 22 - 7075				
Operator on Duty Name	Name of the Person Conducting Inspection Gurfred				
Op	erator Train				
Operator Training current	Oyes	ON _o	OperatorNotified	Yes	Ovo
	tion/Notifica	tion Form			
Is Registration current with correct owner, operator etc.	Yes	\bigcirc No	OperatorNotified	Ves	Oio
	elease Detect	tion			
Release Detection Method	MATG	CIM	SIR	Oic	Other
Make and Model VR-TL>-	356				
Does it have paper?	Yes	O _N o	OperatorNotified	Yes	Q10
Is it in Alarm mode?	Yes	ONo	OperatorNotified	Ores	Olo
Interstitial Monitoring Sensor Status Normal	Yes	No	OperatorNotified	Ores .	Ovo
Necessary Monthly Printout Taken	Yes	ON ₀	OperatorNotified) es	Olo
	Spill Bucke	ts		Ŭ	
Are Spill Buckets Clean and free from water, debris, product etc?	Yes	(9)Vo	OperatorNotified	(P)es	Olo
Are the Spill Bucket in good condition and free of damage/cracks	Yes	₩ _o	OperatorNotified	es	No
	Fill Ports			_	_
Is Fill pipe cap tight and fill pipe free from any obstruction?	Yes	ONO	OperatorNotified	O es	Olo
Pi	ping/STP Su	mps		_	
Are Sumps Clean and free from water, debris, broduct etc?	Yes	₩o	OperatorNotified	Yes	Olo
Under Dispe	nser Contai	nments (UDC))		
Are UDCs clean and free from water, debris, product etc?	Yes	QVo	OperatorNotified	res	Olo
NOTE: ALL LIQUID/DEBRIS OR WASTE MUST BE DISP FOLLOWING PROPER PRO					
Operator on Duty Name		Signature		Date of	P02-1200
나는 그렇게 되었다. 그는 그를 가장 되었다면 되었다. 그는 그를 가장 되었다는 그는 그를 가장 되었다. 그는 그를 가장 그는 그를 다른 그를 다 보는 그를 다 했다.	data@gmail.com Juhres			www.tanksdata.com	
					20220516