
TANK PRESSURE CALCULATION and WATER SENSOR CALIBRATION **Midwest Tank Testing EZY CHEK SYSTEMS DATE AND TIME** 6/7/22 - 1100/1630 316 W. Indiana Ave. 63 - Cloudy **FINAL REPORT WEATHER** Chesterton, IN 46304 INVOICE Collected PC # and WO # TOTAL TANK VOL. NAME and FID# PRODUCT VOL. Citgo - FID # 1634 **ULLAGE VOL.** 1356 Portage Ave **ADDRESS** South Bend IN 46628 **PRODUCT TYPE** Regular CITY/STATE/ZIP TANK# 1 CONTACT **Depth of Groundwater Determined:** 0 **PHONE** BY: **STICK** WHERE: **MONITORING WELL - TANK BED** THE ACOUSTIC CHARACTERISTIC OF A LEAK REVEALS: PASS **TIGHT TANK** THIS UNDERGROUND STORAGE TANK PASSES / FAILS THE CRITERIA SET FORTH BY THE U.S. EPA. **PASS ULLAGE (DRY) PORTION OF LEAK** THIS UNDERGROUND STORAGE TANK PASSES / FAILS THE CRITERIA SET FORTH BY THE U.S. EPA. PASS **BELOW PRODUCT LEVEL (WET) PORTION LEAK** THIS UNDERGROUND STORAGE TANK PASSES / FAILS THE CRITERIA SET FORTH BY THE U.S. EPA. **WATER SENSOR INDICATES:** (MARK ONLY ONE) No Water Intrusion **Water Intrusion Not Applicable** Х **OPERATOR INFO Print Name Adam Case** Certification # 27-1160 Sign Name **Expiration Date** 5/20/24 Adam 800-975-1436 **Testing Company** Midwest Tank Testing Telephone # 316 W. Indiana Ave. **Address** City/State/Zip Chesterton, IN 46304

	Serial Number
IN-TANK MICROPHONE	M1904001/M2106004/M1537006
ACOUSTIC SIGNAL PROCESSOR	E1815004
PRESSURE SENSOR	40665414 and 40665314
WATER SENSOR DISPLAY	D1902350 and D1411504
WATER SENSOR PROBE	P1404102 and P1404106

Calibration Expiration Date	
November-22	

COMMENTS/RECOMMENDATIONS: Water intrusion test was not done because no water was present around the tank.



TANK PRESSURE CALCULATION and WATER SENSOR CALIBRATION **Midwest Tank Testing EZY CHEK SYSTEMS DATE AND TIME** 6/7/22 - 1100/1630 316 W. Indiana Ave. 63 - Cloudy **FINAL REPORT WEATHER** Chesterton, IN 46304 INVOICE Collected PC # and WO # TOTAL TANK VOL. NAME and FID# PRODUCT VOL. Citgo - FID # 1634 **ULLAGE VOL.** 1356 Portage Ave **ADDRESS** South Bend IN 46628 **PRODUCT TYPE** Diesel CITY/STATE/ZIP 3 TANK# CONTACT **Depth of Groundwater Determined:** 0 **PHONE** BY: **STICK** WHERE: **MONITORING WELL - TANK BED** THE ACOUSTIC CHARACTERISTIC OF A LEAK REVEALS: PASS **TIGHT TANK** THIS UNDERGROUND STORAGE TANK PASSES / FAILS THE CRITERIA SET FORTH BY THE U.S. EPA. **PASS ULLAGE (DRY) PORTION OF LEAK** THIS UNDERGROUND STORAGE TANK PASSES / FAILS THE CRITERIA SET FORTH BY THE U.S. EPA. PASS **BELOW PRODUCT LEVEL (WET) PORTION LEAK** THIS UNDERGROUND STORAGE TANK PASSES / FAILS THE CRITERIA SET FORTH BY THE U.S. EPA. **WATER SENSOR INDICATES:** (MARK ONLY ONE) No Water Intrusion **Water Intrusion Not Applicable** Х **OPERATOR INFO Print Name Adam Case** Certification # 27-1160 Sign Name **Expiration Date** 5/20/24 Adam 800-975-1436 **Testing Company** Midwest Tank Testing Telephone # 316 W. Indiana Ave. **Address** City/State/Zip Chesterton, IN 46304

	Serial Number
IN-TANK MICROPHONE	M1904001/M2106004/M1537006
ACOUSTIC SIGNAL PROCESSOR	E1815004
PRESSURE SENSOR	40665414 and 40665314
WATER SENSOR DISPLAY	D1902350 and D1411504
WATER SENSOR PROBE	P1404102 and P1404106

Calibration Expiration Date
November-22

COMMENTS/RECOMMENDATIONS: Water intrusion test was not done because no water was present around the tank.

