Tanks Data	30 DAYS WALK THROUGH			INSPEC	TION
JST Facility I.D.((FID) # 1634	Contact Number				
Facility Name Citgo	Contact email				
Address 1356 Portage Ave South Bend 46628	Date of Inspection 9/8/2		9/8/23	3	
Operator on Duty Name	Name of the Person Conducting Inspection			Rider	
Op	erator Train	ing			
Operator Training current	Yes	ONo	OperatorNotified	Yes	ONO
	ion/Notifica				_
Is Registration current with correct owner, operator etc.	Yes	. ONo	OperatorNotified	Ves	ONO
Release Detection Method	lease Detect	_	Oun	0.0	0
	⊘ ATG	CIM	OSIR	Oic	Other
Make and Model	Franklin	O .	550 evo	0	0
Does it have paper?	Yes	QNo	OperatorNotified	Yes	X10
Is it in Alarm mode?	Q ^{Yes}	\bigcirc No	OperatorNotified	Yes	No.
Interstitial Monitoring Sensor Status Normal	O'es .	O _{No}	OperatorNotified	Ves	No
Necessary Monthly Printout Taken	Yes	ONo	OperatorNotified	Yes	Ovo
	Spill Bucket	ts	imal	_	_
Are Spill Buckets Clean and free from water, debris, product etc?	Yes	⊘ √0 mm	imal OperatorNotified	(Ves	Olo
Are the Spill Bucket in good condition and free of damage/cracks	(√Yes	\bigcirc No	OperatorNotified	Ces	Olo
	Fill Ports	0		_	_
Is Fill pipe cap tight and fill pipe free from any obstruction?	Ves	Olo	OperatorNotified	O es	Olo
	oing/STP Su			0	_
Are Sumps Clean and free from water, debris, product etc?	Yes	Ø/o	OperatorNotified	Ves	O/o
•	A.	nments (UDC		_	_
Are UDCs clean and free from water, debris, product etc?	Yes	(N o	OperatorNotified	(✓) Yes	Olo
NOTE: ALL LIQUID/DEBRIS OR WASTE MUST BE DISP FOLLOWING PROPER PRO	OSSED OFF CEDUE BY	ACCORDINO A CERTIFIED	G TO EXISTING RULES CONTRACTOR.	AND REQU	LATIONS
Operator on Duty Name		Signature	e	Date	
	data@gmail.	com		www.tankso	data.com