30 DAYS WALK THROUGH INSPECTION Tanks Data						
UST Facility I.D.((FID) # 1634	Contact Nur	Contact Number				
Facility Name / TTO	Contact ema	Contact email				
Address 1 3 56 Portage ANR 46616	Date of Insp	Date of Inspection 66-12-2025				
Operator on Duty Name		Name of the Person Conducting Inspection Gurbreet				
0	perator Trainii	ng				
Operator Training current	Yes	ONo	OperatorNotified	Yes	ONo	
The particular property and the particular property of the particular prope	ation/Notification	on Form	O	0		
Is Registration current with correct owner, operator etc.	Yes	CNO	OperatorNotified	Vres	ONO	
	Release Detectio	CIM	SIR	OIC	Other	
Release Detection Method	ATG	Uliw	OBIN	Or o		
Make and Model F 7 5 7 5 5	Yes	No	OperatorNotified	Yes	Oko	
Does it have paper?	\sim	No	OperatorNotified	Ves	ONO.	
Is it in Alarm mode?	Yes	\times .		Yes	\aleph	
Interstitial Monitoring Sensor Status Normal	Yes	QNo	Operator Notified	\times	X'0	
Necessary Monthly Printout Taken	Yes	ONO	OperatorNotified	Yes	ONO	
	Spill Buckets	00-	O			
Are Spill Buckets Clean and free from water, debris, product etc?	Yes	No	OperatorNotified	es	240	
Are the Spill Bucket in good condition and free of damage/cracks	Yes	ONO	OperatorNotified	Oes	ONO	
	Fill Ports		OnewatewNetified	0		
Is Fill pipe cap tight and fill pipe free from any obstruction?	Yes	ON0	OperatorNotified	Oes	Cro	
	iping/STP Sum		OnenatonNetified	Ares	Olo	
Are Sumps Clean and free from water, debris, product etc?	Yes	(V)Vo	OperatorNotified	Ures .	Or	
The state of the s	enser Containn			Over		
Are UDCs clean and free from water, debris, product etc?	Yes	No	OperatorNotified	es	CNO	
NOTE: ALL LIQUID/DEBRIS OR WASTE MUST BE DISP FOLLOWING PROPER PRO	OCEDUE BY A	CCORDING CERTIFIED	CONTRACTOR.			
Operator on Duty Name		Signature	1	Date 0	6-12-10	
317-645-0215 tanks	data@gmail.cor	n gly		www.tanksd	이 유민이 얼마나 있는데 그는 그 아이들이 되었다면 하는데 하는데 살아 되었다. 그렇게 되었다.	
		0			20220516	