Tanks Data	30	DAYS WA	ALK THROUG	H INSPE	CTION
UST Facility I.D.((FID) # 2808	Contact Nun	Contact Number			
Facility Name Marathon	Contact ema	Contact email			
Address 1701 W Jefferson St Plymouth 46563	Date of Inspe	Date of Inspection 3/7/24			
Operator on Duty Name	Name of the Conducting		ler		
0	perator Trainir			Total Sin	
Operator Training current	Oyes	()No	OperatorNotified	Yes	ONo
Registra	ation/Notification	on Form		0	0
Is Registration current with correct owner, operator etc.	Yes	Oyo.	OperatorNotified	Ves	Olo
	elease Detection	The second secon			
Release Detection Method	⊘ ATG	CIM	SIR	OIC	Other
Make and Model	VR				
Does it have paper?	Yes	O _N o	OperatorNotified	Yes	Olo
Is it in Alarm mode?	Yes	ONo.	OperatorNotified	Yes	Olo
Interstitial Monitoring Sensor Status Normal	Yes	Ovo	OperatorNotified	Ves	Olo
Necessary Monthly Printout Taken	Yes	O)No	OperatorNotified	O'es	Olo
	Spill Buckets				
Are Spill Buckets Clean and free from water, debris, product etc?	O/es	(V)Vo	OperatorNotified	(Ves	Olo
Are the Spill Bucket in good condition and free of damage/cracks	(V)/es	No	OperatorNotified	es	No
	Fill Ports				_
Is Fill pipe cap tight and fill pipe free from any obstruction?	Ves	Olo	OperatorNotified	Tes	Olo
	iping/STP Sum			0	
Are Sumps Clean and free from water, debris, product etc?	Yes	⊘ /lo	OperatorNotified	Ves	Olo
	enser Containm	ents (UDC)			
Are UDCs clean and free from water, debris, product etc?	Yes	Ø√0	OperatorNotified	(V) res	Olo
NOTE: ALL LIQUID/DEBRIS OR WASTE MUST BE DISI FOLLOWING PROPER PRO	POSSED OFF ACCEDUE BY A	CCORDING T CERTIFIED C	O EXISTING RULES ONTRACTOR.	AND REQU	LATIONS
Operator on Duty Name		Signature		Date	
	data@gmail.com			www.tanksdata.com	
					20220: