Tanks Date	3	0 DAYS W	ALK THROUGH	INSPEC	TION	
UST Facility I.D.((FID)# 7 RO8	Contact Number					
Facility Name Many & Mon	Contact email					
Address 1701W 50/2220 St 46563	Date of Inspection $07-15-7025$					
Operator on Duty Name	Name of the Person Conducting Inspection Grapheof					
Operator Training current	perator Train	No	OperatorNotified	Ores	ONo	
Is Registration current with correct owner, operator etc.	Yes	Oyo.	OperatorNotified	Ores	Olo	
Release Detection Method	elease Detect	TIM TIM	OSIR	OIC	Other	r
Make and Model VRTLS - 45 Does it have paper? Is it in Alarm mode? Interstitial Monitoring Sensor Status Normal Necessary Monthly Printout Taken	Yes Yes Yes Yes	ONO No No No	OperatorNotified OperatorNotified OperatorNotified OperatorNotified	Yes Yes Yes Yes	800	
Are Spill Buckets Clean and free from water, debris, product etc? Are the Spill Bucket in good condition and free of damage/cracks	Fill Ports	ONO No	OperatorNotified OperatorNotified	es es	810	
Is Fill pipe cap tight and fill pipe free from any obstruction?	Yes iping/STP Su	ımps	OperatorNotified) es	Û\lo	
Are Sumps Clean and free from water, debris, product etc?	Yes	CONO	OperatorNotified	(Wes	Olo	
Are UDCs clean and free from water, debris, product etc?	Yes	inments (UDC)	OperatorNotified		Olo	
NOTE: ALL LIQUID/DEBRIS OR WASTE MUST BE DISI FOLLOWING PROPER PRO	POSSED OF I OCEDUE BY	ACCORDING A CERTIFIED	TO EXISTING RULES CONTRACTOR.		10	
Operator on Duty Name	Signature			Date	4-1) -	707
	sdata@gmail.	.com	>	www.tanks	data.com	2022051