

30 DAYS WALK THROUGH INSPECTION

Tanks Data

UST Facility I.D. (FID) # ~~12808~~ 12808

Contact Number

Facility Name Mesatho

Contact email

Address 1701 W Jefferson St

Date of Inspection

03/18/25

Operator on Duty Name

PLYMOUTH IN-4686563

Name of the Person Conducting Inspection

ANKIT

Operator Training current

☐ Yes ☐ No

Operator Notified

☐ Yes ☐ No

Is Registration current with correct owner, operator etc.

☐ Yes ☐ No

Operator Notified

☐ Yes ☐ No

Release Detection Method

☒ ATG

☐ TIM

☐ SIR

☐ IC

☐ Other

Make and Model

VE 125-400

Does it have paper?

☒ Yes ☐ No

Operator Notified

☒ Yes ☐ No

Is it in Alarm mode?

☒ Yes ☐ No

Operator Notified

☒ Yes ☐ No

Interstitial Monitoring Sensor Status Normal

☒ Yes ☐ No

Operator Notified

☒ Yes ☐ No

Necessary Monthly Printout Taken

☐ Yes ☐ No

Operator Notified

☐ Yes ☐ No

Spill Buckets

☐ Yes ☒ No

Operator Notified

☒ Yes ☐ No

Are Spill Buckets Clean and free from water, debris, product etc?

☐ Yes ☒ No

Operator Notified

☒ Yes ☐ No

Are the Spill Bucket in good condition and free of damage/cracks

☒ Yes ☐ No

Operator Notified

☒ Yes ☐ No

Fill Ports

☐ Yes ☐ No

Operator Notified

☐ Yes ☐ No

Is Fill pipe cap tight and fill pipe free from any obstruction?

☒ Yes ☐ No

Operator Notified

☐ Yes ☐ No

Piping/STP Sumps

☐ Yes ☐ No

Operator Notified

☐ Yes ☐ No

Are Sumps Clean and free from water, debris, product etc?

☐ Yes ☒ No

Operator Notified

☒ Yes ☐ No

Under Dispenser Containments (UDC)

☐ Yes ☐ No

Operator Notified

☐ Yes ☐ No

Are UDCs clean and free from water, debris, product etc?

☐ Yes ☐ No

Operator Notified

☐ Yes ☐ No

NOTE: ALL LIQUID/DEBRIS OR WASTE MUST BE DISPOSED OFF ACCORDING TO EXISTING RULES AND REGULATIONS FOLLOWING PROPER PROCEDURE BY A CERTIFIED CONTRACTOR.

Operator on Duty Name

Signature

Date

317-645-0215

tanksdata@gmail.com

www.tanksdata.com