Tanks Data	30 DAYS WALK THROUGH INSPECTION				
UST Facility I.D.((FID) # 25595	Contact Number				
Facility Name Mobil	Contact email				
Address 29026 CR-20 ElKhart 46517	Date of Inspection 7/19/23				
Operator on Duty Name	Name of the Person Conducting Inspection Josh Rice			ler	
0	perator Train	ing		_	
Operator Training current	Yes	\bigcirc No	OperatorNotified	Yes	O _N o
Registra	ation/Notificat	ion Form		_	
Is Registration current with correct owner, operator etc.	Yes	Û\0	OperatorNotified	Ves	O ₁₀
	Release Detecti	_	<u> </u>	0	<u> </u>
Release Detection Method	ATG	CIM	SIR	OIC	Other
Make and Model	Franklin		550 evo	_	
Does it have paper?	Yes	ON ₀	OperatorNotified	Yes	\bigcirc 10
Is it in Alarm mode?	(V)Yes	O _N o	OperatorNotified	Ves	Olo
Interstitial Monitoring Sensor Status Normal	(V)/es	O/o	OperatorNotified	O'es	Olo
Necessary Monthly Printout Taken	Yes	ON _o	OperatorNotified	O'es	Olo
	Spill Bucket	sini	mal water		
Are Spill Buckets Clean and free from water, debris, product etc?	Ves	(V)/0	mal water OperatorNotified	(Ves	Olo
Are the Spill Bucket in good condition and free of damage/cracks		ON _o	OperatorNotified	Ces	No
•	Fill Ports			0	0
Is Fill pipe cap tight and fill pipe free from any obstruction?	(Ves	Olo	OperatorNotified	(Tes	Olo
	iping/STP Sur	nps		_	
Are Sumps Clean and free from water, debris, product etc?	Yes	\bigcirc 10	OperatorNotified	⊘ Yes	No
	enser Contair	ments (UDC)			0
Are UDCs clean and free from water, debris, product etc?	Yes	⊘ No	OperatorNotified	(V)res	Olo
NOTE: ALL LIQUID/DEBRIS OR WASTE MUST BE DISI FOLLOWING PROPER PRO	POSSED OFF OCEDUE BY A	ACCORDING A CERTIFIED	TO EXISTING RULES CONTRACTOR.	AND REQU	LATIONS
Operator on Duty Name		Signature		Date	
317-645-0215 tanksdata@gmail.com				www.tanksdata.com	
	00				20220