

0000
Tanks Data

30 DAYS WALK THROUGH INSPECTION

UST Facility I.D. (FID) #	25595	Contact Number	
Facility Name	M/D 812	Contact email	
Address	29026 County Rd 20	Date of Inspection	02/27/25
Operator on Duty Name	Sikhani, N. H. 517	Name of the Person Conducting Inspection	ALISHA

	Operator Training current	Registration/Notification Form	Release Detection	Operator Training	Operator Notified	Operator Notified	Operator Notified
Is Registration current with correct owner, operator etc.	☐ Yes	☐ No	☐ Yes	☐ No	☐ Yes	☐ No	☐ No
Release Detection Method							
Make and Model							
Does it have paper?	☒ Yes	☐ No	ATG	FCM	BIR	IC	Other
Is it in Alarm mode?	☒ Yes	☐ No	1-5	550600			
Interstitial Monitoring Sensor Status Normal	☒ Yes	☐ No	☐ Yes	☐ No	☐ Yes	☐ No	☐ No
Necessary Monthly Printout Taken	☒ Yes	☐ No	☐ Yes	☐ No	☐ Yes	☐ No	☐ No
Are Spill Buckets Clean and free from water, debris, product etc?	☒ Yes	☐ No	☐ Yes	☐ No	☐ Yes	☐ No	☐ No
Are the Spill Bucket in good condition and free of damage/cracks	☒ Yes	☐ No	☐ Yes	☐ No	☐ Yes	☐ No	☐ No
Is Fill pipe cap tight and fill pipe free from any obstruction?	☒ Yes	☐ No	☐ Yes	☐ No	☐ Yes	☐ No	☐ No
Are Sumps Clean and free from water, debris, product etc?	☐ Yes	☒ No	☐ Yes	☐ No	☐ Yes	☐ No	☐ No
Are UDCs clean and free from water, debris, product etc?	☒ Yes	☐ No	☐ Yes	☐ No	☐ Yes	☐ No	☐ No

NOTE: ALL LIQUID/DEBRIS OR WASTE MUST BE DISPOSED OF ACCORDING TO EXISTING RULES AND REGULATIONS FOLLOWING PROPER PROCEDURE BY A CERTIFIED CONTRACTOR.

Operator on Duty Name: _____ Signature: _____ Date: _____

317-645-0215 tanksdata@gmail.com www.tanksdata.com