

30 DAYS WALK THROUGH INSPECTION

001

Tank Data

UST Facility I.D. (PID) # 10551

Contact Number

Facility Name MARRIMON

Contact email

Address 2322 W Western Ave, South

Date of Inspection 10/18/24

Operator on Duty Name

Bend, IN 46619

Name of the Person Conducting Inspection AKSHIT

Operator Training current

Operator Training ☐ Yes ☐ No

Operator Notified ☐ Yes ☐ No

Is Registration current with correct owner, operator etc.

Registration/Notification Form ☐ Yes ☐ No

Operator Notified ☐ Yes ☐ No

Release Detection Method

Release Detection ☒ ATG ☐ TIM ☐ SIR

Operator Notified ☐ Yes ☐ No

Make and Model

Does it have paper? ☒ Yes ☐ No

Operator Notified ☐ Yes ☐ No

Is it in Alarm mode?

Is it in Alarm mode? ☒ Yes ☐ No

Operator Notified ☐ Yes ☐ No

Interstitial Monitoring Sensor Status Normal

Operator Notified ☐ Yes ☐ No

Operator Notified ☐ Yes ☐ No

Necessary Monthly Printout Taken

Operator Notified ☐ Yes ☐ No

Operator Notified ☐ Yes ☐ No

Spill Buckets

Are Spill Buckets Clean and free from water, debris, product etc? ☐ Yes ☒ No

Operator Notified ☐ Yes ☐ No

Are the Spill Bucket in good condition and free of damage/cracks

Are the Spill Bucket in good condition and free of damage/cracks ☐ Yes ☒ No

Operator Notified ☐ Yes ☐ No

Fill Ports

Is Fill pipe cap tight and fill pipe free from any obstruction? ☒ Yes ☐ No

Operator Notified ☐ Yes ☐ No

Pipeline/STP Sumps

Are Sumps Clean and free from water, debris, product etc? ☒ Yes ☐ No

Operator Notified ☐ Yes ☐ No

Under Dispenser Containments (UDC)

Are UDCs clean and free from water, debris, product etc? ☐ Yes ☒ No

Operator Notified ☐ Yes ☐ No

NOTE: ALL LIQUID/DEBRIS OR WASTE MUST BE DISPOSED OFF ACCORDING TO EXISTING RULES AND REGULATIONS FOLLOWING PROPER PROCEDURE BY A CERTIFIED CONTRACTOR.

Operator on Duty Name

Signature

Date

317-645-0215

tankdata@gmail.com

www.tankdata.com

20220516