

## **UST TESTING/INSPECTION RESULTS SUMMARY**

OWNER NAME: ADDRESS: CITY/STATE/ZIP: TESTING DATE:	2322 W Western Ave South Bend, IN 46619						LOCATION NAME: LOCATION ADDRESS: LOCATION CITY/STATE: LOCATION FID#:	2322 Sout	ycrest Marathon 2 W Western Ave h Bend, IN 46619 10551
	24,5,2222		THREE YE	AR TESTS/INS	PECTIO	ONS			
PILL BUCKET INTERGR	RITY TESTING	COMPLETED		1	HYL	PROSTATIC SUMP	TEST		NOT PERFORMED HYDROSTATIC
TANK NO	PRODUCT	CONSTRUCTION	RESULT			SUMP ID	MATERIAL	DEPTH	RESULT
1	RUL RUL	Single-Walled Single-Walled	PASS FAIL	ł					
2	PUL	Single-Walled	PASS						
		. 0		1					
				]					
				]					
				]					
VERFILL EQUIPMENT	INSPECTION	NOT PERFORMED			OVI	ERFILL ALARM TES	т	COMPLETED	
			BALL FLOAT RESULT	AUTO SHUT					
TANK	PRODUCT	TYPE	RESULI	OFF RESULT		TANK	PRODUCT	BRAND/MODEL	RESULT
						1 1	RUL RUL	VEDEER ROOT VEDEER ROOT	FAIL FAIL
						2	PUL	VEEDER ROOT	FAIL
						_			
LEGEND:									
RUL	Regular Unleaded								
DSL	Diesel								
PUL	Premium Unleaded								
KER	Kerosene								
ODSL REC	Off Road Diesel Recreational								
REC	Recreational								
RECOMMEN	DATIONS:								
									-




# SITE PHOTOS

TEST DATE:	10/9/2023
LOCATION NAME:	Marycrest Marathon
LOCATION ADDRESS:	2322 W Western Ave
LOCATION CITY/STATE:	South Bend, IN 46619
LOCATION PHONE:	317-645-0215
LOCATION CONTACT:	Virendar Kumar

OWNER NAME:	Tanks Data
OWNER ADDRESS:	2322 W Western Ave
OWNER CITY/STATE/ZIP:	South Bend, IN 46619
LOCATION FID#:	10551
WORK ORDER NO:	NE-0562



### **AUDIBLE ALARM**



**RUL1 SPILL BUCKET TEST START 14"** 



**RUL1 SPILL BUCKET TEST END 14"** 





# SITE PHOTOS

TEST DATE:	10/9/2023
LOCATION NAME:	Marycrest Marathon
LOCATION ADDRESS:	2322 W Western Ave
LOCATION CITY/STATE:	South Bend, IN 46619
LOCATION PHONE:	317-645-0215
LOCATION CONTACT:	Virendar Kumar

OWNER NAME:	Tanks Data	
OWNER ADDRESS:	2322 W Western Ave	
OWNER CITY/STATE/ZIP:	South Bend, IN 46619	
LOCATION FID#:	10551	
WORK ORDER NO:	NE-0562	

**RUL2 SPILL BUCKET TEST START 12.75"** 





**PUL SPILL BUCKET TEST START 13.25"** 







### **CERTIFICATION VERIFICATION**

Tanks Data 2322 W Western Ave South Bend, IN 46619

Testing Date: 10/9/2023

Marycrest Marathon
Location of Test: 2322 W Western Ave

South Bend, IN 46619

Site FID#: 10551

Service Technican: Certified Technician: ADAM WILDER 0

Midwest ECS has completed the following tests/inspections at the above noted location:

ATG Functionality	
Leak Detector	
Elec Line Leak Detector	
Product Line Testing	
Liquid Sensor Functionality	
Spill Bucket	Х
Containment Hydrostatic Sump	
Overfill Equipment Inspection	
Overfill Alarm	Х
Vent Valve	
Interstital	
Non-Volumetric Tank Tightness	
Shear Valve Inspection	

I,ADAM WILDER, the certified technician, was present throughout the duration of the testing and/or inspection performed by Midwest ECS at the above address on the above date. I affirm that the testing was done in accordance with Rule 329 IAC 9 and 40CFR Part 80, is accurate based upon the results received and that these forms accurately reflects the results of the testing and/or inspection.

Technician Signature:	\ <b>!</b>
echnician Printed Name:	ADAM WILDER

Date & Time: 10/09/2023 @ 11:30AM



### INDIANA HOMELAND SECURITY



#### **Underground Storage Tank**

ADAM P WILDER 500 SIMS STREET FRANKFORT, INDIANA

FRANKFORT, INDIA

DISCIPLINES

✓ Installation or Retrofitting

Decommissioning Closure

Cathodic Protection

Decommissioning Removal

Testing

EXPIRATION

01/23/2025

 $I\,attest\,with\,my\,signature\,below,\,that\,this\,technician\,was\,present\,onsite\,for\,testing\,as\,described\,above.$ 

