Tanks Data		30 DAYS V	VALK THROUG	HINSPE	CTION	
UST Facility I.D.((FID) # / 0 55/	Contact Number					
Facility Name 1990		Contact runnoci				
Address 2377 W Gestom A 104%	710	Date of Inspection 19-75-2075				
Operator on Duty Name	A STATE OF THE PARTY OF THE PAR	rtenierouritooriputtusementseksplassessess		0		
	Name of the Person Conducting Inspection  Sung/8 0 0					
	Operator Train		P C			
Operator Training current	Yes	ONo	OperatorNotified	Yes	(No	
Le Registration automial Registr	ation/Notifica	tion Form				
Is Registration current with correct owner, operator etc.	Yes	(No	OperatorNotified	Yes	Oio	
Release Detection Method	Release Detect					
Make and Model 1/4/5	ATG	CIM	SIR	OIC	Other	
Does it have paper?	15 U		0			
Is it in Alarm mode?	Yes	No.	OperatorNotified	Yes	Q10	
	Yes	No	OperatorNotified	Yes	Oio	
Interstitial Monitoring Sensor Status Normal	Yos	(No	OperatorNotified	Yes	Oio	
Necessary Monthly Printout Taken	Yes	ONO	OperatorNotified	res	Olo	
	Spill Buckets					
Are Spill Buckets Clean and free from water, debris, product etc?	Yes	No	OperatorNotified	es	Oio	
are the Spill Bucket in good condition and free of damage/cracks		()No	OperatorNotified	es	No	
Is Fill nine can tight and fill nine for form	Fill Ports					
Is Fill pipe cap tight and fill pipe free from any obstruction?	Yes	(No	OperatorNotified	Tes	Olo	
Are Sumps Clean and free from water, debris, product etc?	ping/STP Sum	ps				
	Yes	ENO.	OperatorNotified	Yes	(No	
Are UDCs clean and free from water, debris, product etc?	nser Containr	1				
	Yes	No	OperatorNotified	Tes	Olo	
NOTE: ALL LIQUID/DEBRIS OR WASTE MUST BE DISPO FOLLOWING PROPER PRO	OSSED OFF A CEDUE BY A	CCORDING 1 CERTIFIED C	ONTRACTOR	AND REQU	LATIONS	
rator on Duty Name		Signature		Date		
317-645-0215				Date		
tanksd	ata@gmail.com	@gmail.com			www.tanksdata.com	
		4			2022	