Tanks Data		30 DAYS V	VALK THROUG	H INSPE	CTION	
UST Facility I.D.((FID)# 055 (	Contact 1	Contact Number				
Facility Name Marathon	Contact e	Contact email				
Address 2 37 2 W 2. 02 form A1, 09 6619	Date of I	Date of Inspection 07-79-79-7035				
Operator on Duty Name		Name of the Person Conducting Inspection				
0	perator Trai					
Operator Training current	Yes	ONo	OperatorNotified	Yes	ONo	
Registra	tion/Notifica	ation Form				
Is Registration current with correct owner, operator etc.	Yes	ONo	OperatorNotified	Ves	Oio	
	elease Detect	A	O	000		
Release Detection Method	MATG	SIM	SIR	Oic	Other	
Make and Model VRTUS-35	6	<u> </u>		O.	0	
Does it have paper?	Yes	QNo.	OperatorNotified	Yes	No.	
Is it in Alarm mode?	(PYes	ONO	OperatorNotified	Yes	Q\vo	
Interstitial Monitoring Sensor Status Normal	Yes	Ovo	OperatorNotified	() Yes	QNo.	
Necessary Monthly Printout Taken	Yes	ONo	OperatorNotified	Ores	Olo	
	Spill Bucket	s				
re Spill Buckets Clean and free from water, debris, product etc?	Yes	( No	OperatorNotified	(T)es	Olo	
re the Spill Bucket in good condition and free of damage/cracks	(G)Yes	No	OperatorNotified	es	Olo	
	Fill Ports			_		
Is Fill pipe cap tight and fill pipe free from any obstruction?	Yes	ONO	OperatorNotified	Tes	Olo	
Pip	ing/STP Sun	nps		0		
Are Sumps Clean and free from water, debris, product etc?	Yes	(D)Vo	OperatorNotified	4 Tes	Olo	
Under Dispen	ser Contain	ments (UDC)				
Are UDCs clean and free from water, debris, product etc?	Yes	No	OperatorNotified	Tes	Olo	
NOTE: ALL LIQUID/DEBRIS OR WASTE MUST BE DISPO FOLLOWING PROPER PROC				AND REQU	LATIONS	
ator on Duty Name		Signature		Date O	7-29-70	
317-645-0215 tanksda	ta@gmail.co	om /		www.tanks	data.com	
					2022051	