

000

TRAFFIC DATA

30 DAYS WALK THROUGH INSPECTION

UST Facility I.D. (FID) # 14301

Facility Name AMCC

Address 59572 Mayflower Rd South

Operator on Duty Name Budan Yabli

Name of the Person Conducting Inspection AKSMIT

Operator Training current

Operator Training

Operator/Notified

Yes No

Is Registration current with correct owner, operator etc.

Registration/Notification Form

Operator/Notified

Yes No

Release Detection Method

Release Detection

SIR

Yes No Other

Make and Model

CR TCS 350

Does it have paper?

Yes

Operator/Notified

Yes No

Is it in Alarm mode?

Yes

Operator/Notified

Yes No

Interstitial Monitoring Sensor Status Normal

Necessary Monthly Printout Taken

Yes

Operator/Notified

Yes No

Spill Buckets

Are Spill Buckets Clean and free from water, debris, product etc?

Yes

Operator/Notified

Yes No

Are the Spill Bucket in good condition and free of damage/cracks

Yes

Operator/Notified

Yes No

Fill Ports

Is Fill pipe cap tight and fill pipe free from any obstruction?

Yes

Operator/Notified

Yes No

Piping/STP Sumps

Are Sumps Clean and free from water, debris, product etc?

Yes

Operator/Notified

Yes No

Under Dispenser Containments (UDC)

Are UDCs clean and free from water, debris, product etc?

Yes

Operator/Notified

Yes No

NOTE: ALL LIQUID/DEBRIS OR WASTE MUST BE DISPOSED OFF ACCORDING TO EXISTING RULES AND REGULATIONS FOLLOWING PROPER PROCEDURE BY A CERTIFIED CONTRACTOR.

Operator on Duty Name

Signature

Date

317-645-0215

tanksdata@gmail.com

www.tanksdata.com