Tanks Data		30 DAYS	WALK THROU	GH INSPI	ECTION
UST Facility I.D.((FID)#	Contact N	Contact Number			
Facility Name HMOCO	Contact en	Contact email			
Address 5 957 2 may Cower Rd9	6614 Date of Ins	Date of Inspection 09-25-2025			
Operator on Duty Name		Name of the Person Conducting Inspection Guylact			
Operator Training current	Operator Train Yes	ing (No	OperatorNotified)Yes	Ovo
Is Registration current with correct owner, operator etc.		No	OperatorNotified	Ores	Oio
Release Detection Method	Release Detection	CIM	OSIR	OIC	Other
Make and Model VRTU Does it have paper?) - 35 Yes	QNo	OperatorNotified	Yes Yes	Qio No
Is it in Alarm mode?	Yes	No	OperatorNotified	\times	No
Interstitial Monitoring Sensor Status Normal Necessary Monthly Printout Taken	Yes	No	OperatorNotified OperatorNotified	res	Ovo
Necessary Monthly Fintout Taken	Spill Buckets	0			
Are Spill Buckets Clean and free from water, debris, product Are the Spill Bucket in good condition and free of damage/cra	etc? Ores	ONO No	OperatorNotified OperatorNotified	Oes es	Sio No
Is Fill pipe cap tight and fill pipe free from any obstruction		ONO	OperatorNotified	Oes	Olo
Are Sumps Clean and free from water, debris, product etc?	Yes	Olo	OperatorNotifled	Ores	Olo
	Dispenser Containme	No No	OperatorNotified	⊘ és	No
Are UDCs clean and free from water, debris, product etc?	VICEO OFF AC	VX /		ND REQULA	ATIONS
NOTE: ALL LIQUID/DEBRIS OR WASTE MUST BE D FOLLOWING PROPER I	PROCEDUE DI A C.	CRITICITY	ONTRACTOR.	Date	
Operator on Duty Name		Signature		www.tanksda	ta.com
	nksdata@gmail.com			12.12.11.1 Medical Constitution	2022051