

TRIENNIAL INSPECTION

Facility Name: SR 23 PROPERTY, LLC Test Date: 03/27/2025
Facility Address: 59572 MAYFLOWER ROAD SOUTH BEND IN ...
Facility ID: 14301

UST CONTAINMENT SUMP INTEGRITY TESTING: HYDROSTATIC

Test Type/Reason: Triennial

Sump Name	Dsl stp	Premium stp	Udc 1/2	Udc 7/8	
Clean of liquid/debris	YES	YES	YES	YES	
VISUAL INSPECTION	PASS	PASS	PASS	PASS	
Test Start Time	1:00	1:00	1:00	1:00	
Test End Time	2:00	2:00	2:00	2:00	
Starting Water Level (in)	40	42	10	9	
Ending Water Level (in)	40	42	10	9	
Water Level Change (in)	0	0	0	0	
TEST RESULT	PASS	PASS	PASS	PASS	

Sump Name					
Clean of liquid/debris					
VISUAL INSPECTION					
Test Start Time					
Test End Time					
Starting Water Level (in)					
Ending Water Level (in)					
Water Level Change (in)					
TEST RESULT					

Comments

--

Technician Name: Blake Zylstra
Dispatch # 413141
B&K Equipment completes testing and inspections per recommended practices of PEI RP1200-19