001	3	30 DAYS WALK THROUGH INSPECTION				
JST Facility LD.((FID)# 7 6 9	Contact Nu	Contact Number				
acility Name Phy (1/23-56	-	Contact email				
Address 1606 Cd32, 12018 54 C-019		Date of Inspection 07 - 23 - 2025				
Operator on Duty Name	Name of th	Name of the Person				
			wyeres			
	perator Train	ing	/	O.		
Operator Training current	Yes	ON <sub>0</sub>	OperatorNotified	Ores.	ONO 1	
	ation/Notificat			0		
Is Registration current with correct owner, operator etc.	Yes	ON <sub>0</sub>	OperatorNotified	Ures	000	
	Release Detecti	ion		000		
Release Detection Method	ATG	CIM	SIR	Oic	Other	
Make and Model UR7 CS-3	90			_		
Does it have paper?	Yes	ONo	OperatorNotified	QY'es	Q10	
Is it in Alarm mode?	Yes	No	OperatorNotified	()Yes	Q\o	
Interstitial Monitoring Sensor Status Normal	Yes	No	OperatorNotified	Ores	Olo	
Necessary Monthly Printout Taken	Yes	No	OperatorNotified	Cycs	(No	
14cccssary Wiolithly Fillitout Taxon	Spill Bucket					
		(9x0	OperatorNotified	Dos	(No	
Are Spill Buckets Clean and free from water, debris, product etc?	><.	×	OperatorNotified	X	Xio	
Are the Spill Bucket in good condition and free of damage/cracks		ONO	Operatorivouneu	0		
	Fill Ports		OperatorNotified	Ores	Oko	
Is Fill pipe cap tight and fill pipe free from any obstruction?	Yes	ON <sub>0</sub>	OperatorNottneu	000		
	Piping/STP Su	mps .	Oto-Notified	(Au	$\bigcirc$	
Are Sumps Clean and free from water, debris, product etc?	Ves	TONO .	OperatorNotified	Vres.		
	enser Contai	nments (UDC)		6		
Are UDCs clean and free from water, debris, product etc?	OY'es	ON0	OperatorNotified		Ovo.	
NOTE: ALL LIQUID/DEBRIS OR WASTE MUST BE DIS FOLLOWING PROPER PR	POSSED OFF OCEDUE BY	ACCORDING A CERTIFIED	TO EXISTING RULES CONTRACTOR.	S AND REQU	JLATIONS	
Operator on Duty Name		Signature		Date O	0 -	
	csdata@gmail.	ata@gmail.com			sdata.com	

Market State of the Control of the C