Tanks Data	30 DAYS WALK THROUGH INSPECTION				CTION		
IST Facility I.D.((FID)# 264		Contact Nu	Contact Number				
Facility Name Phillips 66		Contact email					
Address 1606 Cassabolis + 46519		Date of Inspection 66-26-2025					
Operator on Duty Name		Name of the Person Conducting Inspection  Guesbreet					
	0	perator Train					
Operator Training current		Yes	ONo	OperatorNotified	Yes	ONo	
Is Registration current with correct owner, operator etc.		Yes	Oµ0	OperatorNotified	O'res	Olo	
		elease Detect	ion	O	0.0		
The second secon	Detection Method	ATG	CIM	SIR	Oic	Other	
	it have paper?	Yes	ONo	OperatorNotified	Yes	Oto	
Is it in Alarm mode?		Yes	No	OperatorNotified	Yes	Olo	
Interstitial Monitoring Sensor Status Normal		Yes	No	OperatorNotified	Yes	ONO	
Necessary Monthly Printout Taken		Yes	No	OperatorNotified	Tes	No	
		Spill Bucket	s		_		
Are Spill Buckets Clean and	free from water, debris, product etc?	· · · · ·	(CNO	OperatorNotified	Pes	O40	
Are the Spill Bucket in good condition and free of damage/cracks			No	OperatorNotified	es	No	
		Fill Ports	_				
Is Fill pipe cap tight and f	fill pipe free from any obstruction?	O'es	Ovo	OperatorNotified	Oes	Olo	
	P	iping/STP Su	_				
Are Sumps Clean and fro	ee from water, debris, product etc?	Yes	(D)10	OperatorNotified	Ves	Oyo	
		enser Contain	^				
	e from water, debris, product etc?	Yes	ONO	OperatorNotified	$\sim$	Oyo	
NOTE: ALL LIQUID/DEBRIS OR WASTE MUST BE DISPOSSED OFF ACCORDING TO EXISTING RULES AND REQULATIONS FOLLOWING PROPER PROCEDUE BY A CERTIFIED CONTRACTOR.							
Operator on Duty Name			Signature	-~	Date O	5-20-202	
317-645-0215 tanksd		sdata@gmail.	com your		www.tank		
						20220516	