

TRIENNIAL INSPECTION

Facility Name: QUICK MART Test Date: 04/03/2025

Facility Address: 1606 CASSOPOLIS STREET ELKHART IN 46514 Facility ID: 264						
OVERFILL PREVENTION BALL FLOAT INSPECTION						
Tank ID #	T2					
Product	PUL					
Ball Float Valve Inspection						
Tanktop fittings vapor-tight and leak-free?	YES					
Ball float cage free of debris?	YES					
Ball free of holes and cracks and moves freely in cage?	YES					
Vent hole in pipe open and near top of tank?	YES					
Ball float pipe proper length to restrict float at 90% of tank capacity?	YES					
INSPECTION RESULT	PASS					
Comments						

Technician Name: Jack Davids

Dispatch # 413676

B&K Equipment completes testing and inspections per recommended practices of PEI RP1200-19